

PEOPLESFIRST

Website Quality Assurance Report

Design Fidelity • Responsive QA • Usability • Form Validation

Document type	Consolidated QA / Design Review
Primary reference	PeopleFirst Figma design
Coverage	Desktop, Mobile and Tablet
Prepared from	Original 26-page annotated QA report

1. Executive Summary

This report restructures the original annotated QA review into a professional, trackable format. The findings focus primarily on visual fidelity to the Figma design, spacing and typography consistency, responsive behavior, floating side-navigation usability, and contact-form validation. The original screenshots and annotations are retained as evidence throughout the report.

Desktop QA	Mobile QA	Tablet QA
Landing, Home, Contact, About, Grow With Us, Ideas Lab, Insights/Studio, What We Do and Podcasts	Home, About, What We Do, Ideas Lab, Grow With Us and Insights	Home, About, What We Do, Podcasts, Grow With Us and Insights

2. QA Priorities

- Bring all page sections back into visual parity with the approved Figma design: spacing, proportions, colors, border radius, shadows, gradients, decorative graphics and iconography.
- Normalize typography across the site. The source report repeatedly flags font family, font size, font weight and letter-spacing inconsistencies.
- Fix responsive collisions, clipping and unavailable sections at mobile/tablet breakpoints.
- Ensure the floating side navigation remains usable without covering footer links or page controls.
- Improve Contact Us validation with field-level format checks, sensible maximum lengths and consistent autofill styling.

3. Review Method & Scope

The original QA report compares the implemented PeopleFirst website against the Figma design using annotated desktop, mobile and tablet screenshots. This reformatted report preserves those observations, groups them by page/section, assigns unique tracking IDs, and expresses each note as a clear finding plus required correction. No new functional requirements are introduced beyond what is visible or stated in the source report.

4. Desktop QA Findings

Landing Page

ID	Category	Finding	Required correction
LND-01	Visual fidelity	Top-of-page visualization does not match the Figma design.	Match the composition, placement and scale to Figma.
LND-02	Navigation / Typography	Navigation labels such as Home and Podcasts sit slightly high, are spaced too far apart and use different font sizing.	Align labels vertically and match spacing and font size to the design.

ID	Category	Finding	Required correction
LND-03	Heading layout	In “INSIGHTS BY PEOPLE FIRST”, “PEOPLE FIRST” wraps below “Insights By”.	Keep the heading arrangement consistent with the design.
LND-04	Footer navigation	Highlighted footer navigation under the address uses a different color from the design.	Use the Figma highlight color.
LND-05	Iconography	The message icon does not match the design.	Replace with the correct design icon.
LND-06	Responsive	On mobile and tablet, the PeopleFirst graphic touches the Home icon.	Add/adjust responsive spacing.
LND-07	Responsive	Up to approximately 568 px, the PeopleFirst graphic overlaps the Home icon and footer navigation layout breaks.	Prevent overlap and preserve footer link layout at small widths.


PeopleFirst Website QA:

In desktop:



Landing page:

1. Visualization from top of the page is not matched with the figma design.
2. The texts like podcasts, home etc are placed slightly above and are placed at some more distance, Moreover, their font size are not same.
3. In "INSIGHTS BY PEOPLE FIRST", **PEOPLE FIRST** is placed under the Insights By.
4. The footer navigation highlighted under address, color doesn't match with design.
5. The message icon not matched




6. In mobile view, the PeopleFirst image should not touch the home icon and same issue in tablet View.
7. In second mobile view, till the width of 568px, the PeopleFirst image overlaps with home icon, and For Footer navigation links, layout disturbs.


Home Page - Hero

ID	Category	Finding	Required correction
HOM-01	Visual artifact	A green half-shadow appears at the left-center area.	Remove or match the intended design treatment.
HOM-02	Spacing	“Partner with Us”, “Join Training Program” and the message icon do not have the spacing shown in Figma.	Match horizontal spacing and button/icon placement.
HOM-03	Responsive	On some mobile widths, a decorative/visual element overlaps the text.	Adjust responsive positioning so text remains unobstructed.
HOM-04	Design fidelity	Background and side-icon line colors/placement differ from the reference design.	Match background treatment, icon colors and vertical placement.

Home Page:




8. In this home page, there is green half shadow in left center position.
9. "Partner with Us" and "Join Training Program" button and "message icon" needs space between them according to design.




Home Page - Featured Work & Tech Events

ID	Category	Finding	Required correction
HOM-05	Featured Work	Heading/underline and decorative elements do not fully match Figma; additional spacing is needed in mobile view.	Align decorative marks and add the required mobile spacing.
HOM-06	Featured Work	Several decorative accents/lines appear absent or positioned differently.	Match the complete Figma composition and spacing.
HOM-07	Tech Events	Image/text positions and decorative elements differ from the design.	Correct alignment, image placement and decorations.
HOM-08	Tech Events	Stats/labels and some text positioning do not match the reference.	Match typography, label position and spacing to Figma.

Home ---> Feature Page:




Home----> TechEvents:




Home Page - Cards & Gallery

ID	Category	Finding	Required correction
HOM-09	Cards	Horizontal and vertical gaps are inconsistent.	Use equal, consistent card spacing.
HOM-10	Cards	Borders, card content/brand marks and some decorative content do not match the design.	Match border treatment, logos and card content placement.
HOM-11	Cards / Mobile	Card font size should be reduced and internal padding increased for a cleaner mobile layout.	Reduce text size and increase heading-to-paragraph padding.
HOM-12	Gallery	Gallery color treatment differs from the design.	Use the design colors/gradient.
HOM-13	Gallery / Mobile	More bottom margin is needed.	Increase bottom spacing to match the design.

Home-----> CardsSection:




Home-----> OurGallery:



Home Page - Testimonials & Ecosystem

ID	Category	Finding	Required correction
HOM-14	Testimonials	Card sizes do not match the design.	Match card dimensions and grid proportions.
HOM-15	Testimonials	Text content inside cards differs from the design.	Use the approved testimonial copy.
HOM-16	Testimonials	Profile pictures are used where the design shows name initials/letters.	Use the design's avatar treatment.
HOM-17	Testimonials	@username color differs from the design.	Apply the correct color.
HOM-18	Testimonials	Hashtag top spacing is too large.	Reduce hashtag top margin/padding.
HOM-19	Testimonials	Hashtag wording differs from the design.	Use the approved hashtag text.
HOM-20	Testimonials	Border radius is larger than the design.	Reduce card corner radius.
HOM-21	Ecosystem	The section needs more top spacing; edge images should sit higher.	Increase top margin and reposition edge graphics.
HOM-22	Ecosystem	Several colors, font weights, decorative shapes and logo/graphic sizes differ from Figma.	Match visual styling and positioning to the design.

Home -----> Testimonial:




10. Cards sizes doesn't match with design.
11. Text inside cards are also not same.
12. Profile picture is uploaded instead of name letter.
13. @username color not match.
14. #hashtags like #another ,their top margin/padding should be less according to design.
15. #hashtags words are not same.
16. Border radius value should be decreased.

Home ----->Compounding Corporate/ Ecosystem:




Home Page - Story & Footer

ID	Category	Finding	Required correction
HOM-23	Section spacing	More space is needed between the preceding ecosystem section and The Story.	Increase vertical separation between sections.
HOM-24	The Story	Background/text colors, icon placement, image sizes and border/shape details do not match the design.	Match colors, image proportions and decorative elements to Figma.
HOM-25	The Story	Some body/annotation text appears slightly larger than the design.	Reduce typography to the design size.



Need space btw 2 sections.


Home----> TheStory:



Home Page - Footer

ID	Category	Finding	Required correction
HOM-26	Footer layout	Logo/social icons, footer link spacing, borders and text styling do not match the design.	Align footer structure, spacing and typography to Figma.
HOM-27	Side navigation	Padding around the floating side icons is inconsistent; other icons should be checked as well.	Normalize icon container padding and alignment.


Home-----> Footer




Contact Us Page

ID	Category	Finding	Required correction
CON-01	Background	The design uses a white/blurred background treatment that is not matched.	Apply the Figma background treatment.
CON-02	Layout / UX	The full-height/scrolling implementation feels less smooth; the minimized version shown in the report better matches the intended design.	Use the compact composition and avoid unnecessary internal scrolling.
CON-03	Form validation	Name, Email and Phone fields do not have maximum-length limits.	Add appropriate maximum lengths.
CON-04	Form validation	Invalid email/phone formats are only surfaced after submission; phone should reject letters and email should require valid format.	Add clear field-level validation and messages.
CON-05	Form styling	Autofilled fields appear light blue.	Override autofill styling to preserve the design.
CON-06	Iconography	Left-side contact icons do not match Figma, especially the email icon; corner radius also differs.	Use the correct icons and reduce the specified radius.
CON-07	Button styling	The “Say Hello” button/icon treatment appears blurred although the design is not.	Use a crisp, non-blurred treatment.

Contact Us Page:



White and blur bg color in design.



"Say Hello" btn is not blurred in the design.


17. The first contact us image is made by following the figma design, but there is scroll effect which make site less attractive and smooth for user. The second image is minimized version of the first contact us image which is actually according to the figma design. It gives more smooth look.
18. The Name,Email and Phone fields have no letters max-limit.
19. If user not follow the format as required in the email and phone fields such as "@" sign is necessary and in the phone fields letters not needed instead of number , for both of them there should be some message for the user to avoid using them while filling the fields data. He gets this message he fills all the fields and enter the submit button.
20. Autofill fields give light blue color.
21. In the left side the icons used not match with the design, specially for second one, icon of gmail, the border radius should be less.

About Us Page


ID	Category	Finding	Required correction
ABT-01	Iconography	The “Say Hello” message icon does not match the design.	Use the correct message icon.
ABT-02	CTA layout	Partner/Training CTA area and surrounding elements show alignment differences.	Match CTA placement and spacing to Figma.
ABT-03	Journey cards	Card details, button/arrow placement and spacing require closer design matching.	Align card content and controls to the reference.



About Us Page:




22. Say Hello's message icon not same as in design.



About Us - Stats, Partners, Vision & Mission

ID	Category	Finding	Required correction
ABT-04	Typography	Font family differs from the design in the Key Stats area.	Use the approved font family consistently.
ABT-05	Stats	Stats box sizes/positions and internal labels differ from Figma.	Match dimensions and placement.
ABT-06	Partners slider	Current single-row slider differs from the more attractive two-row design behavior.	Implement the two-row entrance/exit behavior shown in Figma.
ABT-07	Vision & Mission	Spacing, decorative orientation, image placement and some text styling differ.	Match the full Figma composition.





23. Slider not same as in design. It is ok but the slider made in design look more attractive if they are in 2 rows as in design, from one row it enters and leaves from 2nd row.



About Us - Mission, Journey & Footer



ID	Category	Finding	Required correction
ABT-08	Mission content	Icons/graphics, text orientation and some colors differ from the design.	Match icons, orientation and colors.
ABT-09	Journey selector	Card colors, labels/icons and overall treatment do not match Figma.	Use the exact design styles for all four journey options.
ABT-10	CTA strip	Border radius and spacing differ from the design.	Match CTA strip radius and spacing.
ABT-11	Footer	Too much white space above the About Us footer.	Reduce the empty vertical space.
ABT-12	Footer / Side icons	Side-icon labels make footer links harder to use.	Prevent side navigation from obstructing footer interactions.
ABT-13	Footer alignment	Footer columns need tighter spacing; bottom alignment should match the contact line.	Refine column spacing and vertical alignment.



Grow With Us Page - Hero & Program Areas



ID	Category	Finding	Required correction
GRW-01	Hero alignment	Logo/left artwork alignment and spacing do not match the design.	Match the reference alignment.
GRW-02	Typography	Font weight and font family differ in the hero.	Use the design typography.
GRW-03	Hero visual	Image/artwork styling differs from Figma.	Use the correct image treatment.
GRW-04	Why These Programs Exist	Image height and visual treatment differ from the design.	Match image dimensions and styling.
GRW-05	CTA buttons	Button positions, first-button color and message icon differ.	Match CTA styling and placement.
GRW-06	Program Areas	Decorative elements, card imagery and heading/icon treatment differ.	Match cards and decorative visuals to Figma.

Grow With Us Page :



Grow With Us - Additional Cards & Outcomes




ID	Category	Finding	Required correction
GRW-07	Typography	Font size, weight and family are inconsistent with the design.	Normalize typography across these cards.
GRW-08	Card layout	Program cards need spacing/alignment refinement; report notes an extra card could fit in available area.	Rebalance the grid and use available space consistently.
GRW-09	Who Can	Bullet/graphic styling and layout differ from Figma.	Match the design's list presentation.
GRW-10	Program Outcomes	Outcome card spacing and illustration placement should be checked against Figma.	Align content and imagery consistently.



Ideas Lab Page


ID	Category	Finding	Required correction
IDL-01	Hero	Hero image/illustration does not match the design.	Use the Figma visual.
IDL-02	Background	Background color/treatment is not the same.	Match the design background/gradient.
IDL-03	Typography	Heading font size/weight differs from Figma.	Use approved typography.
IDL-04	Article cards	Heading style, image border radius/gradient, image position and decorative graphics differ.	Match card visuals, image treatment and placement.

Ideas Lab Page:




Studio Page - Insights by PeopleFirst

ID	Category	Finding	Required correction
STD-01	Filter area	Border color differs from the design.	Use the correct border color.
STD-02	Cards	Border radius differs from Figma.	Use the specified radius.
STD-03	Header	Logo size should be reduced and alignment should match the design.	Reduce logo size and align header controls.
STD-04	Hero/card visual	Decorative image and large content image do not fully match the design.	Use the correct images and positions.




Studio Page (Insights by PeopleFirst):





What We Do Page - Ecosystem

ID	Category	Finding	Required correction
WWD-01	Impact graphic	Decorative/logo elements and graph presentation differ from Figma.	Match graphics, spacing and composition.
WWD-02	Ecosystem cards	Card colors, border radius, icons, text colors and alignment differ.	Match all card styling to the design.
WWD-03	Typography	Several titles/body styles do not match Figma.	Normalize font family, weight and spacing.




What We Do PAGE :



What We Do - Ventures & Results

ID	Category	Finding	Required correction
WWD-04	CTA/decorations	Decorative marks and CTA button position differ from the design.	Correct decorations and CTA placement.
WWD-05	Venture cards	Card sizes/colors/gradients, icons and alignment differ from Figma.	Match card grid, colors and iconography.
WWD-06	Results section	Overall layout/design does not match; heading needs more letter spacing.	Recreate the section to the Figma layout and adjust tracking.



What We Do - Impact Focus & Brand Architecture

ID	Category	Finding	Required correction
WWD-07	Impact Focus	Right-side shadow, card widths, font weights, image sizing/orientation and text spacing differ.	Match shadow, proportions, image treatment and typography.
WWD-08	Brand Architecture	Font family does not match and spacing around heading/body needs adjustment.	Use the design font and spacing.
WWD-09	Architecture cards	Shadows and body text weight differ from Figma.	Match card shadow and text styling.



BRAND ARCHITECTURE

The Three Dimensions of Holistic Evolution

check the design

font-family not matched

space in all should be equal


The People First Evolution Model divides development into three distinct operational circles — Physical, Mind, and Market — because true economic empowerment must mirror the natural progression of human capability.

We build the foundation, cultivate potential, and create the pathways that lead our people to lasting prosperity.





What We Do - Evolutionary Pipeline & Dimensions

ID	Category	Finding	Required correction
WWD-10	Typography	Font family is inconsistent across the section.	Use one approved font family throughout.
WWD-11	Pipeline	Letter spacing, card widths, center text/image sizes and footer strip details differ.	Match Figma proportions, spacing and labels.
WWD-12	Brand Architecture cards	Family/weight, color accents, icon sizing and shadow treatment differ.	Match the design styling consistently.




Podcast Page

ID	Category	Finding	Required correction
POD-01	Hero	Logo/graphic shadow, microphone/image sizing and title typography differ from Figma.	Match visual scale, shadow and typography.
POD-02	Podcast Value	Border radius, border, background color, image position and shadow differ from the design.	Match the card treatment and image placement.
POD-03	CTA	CTA button placement does not match the design.	Align CTA controls to Figma.
POD-04	Iconography	Message icon is missing.	Add the design message icon.
POD-05	Studio section	Alignment and line/graphic presentation require closer design matching.	Match the Figma composition.





Message icon missing




Podcast Page - Listing & Footer

ID	Category	Finding	Required correction
POD-06	Podcast cards	Titles, images and “largest digital...” stat-box color should be checked across all podcast entries.	Standardize every podcast card to the design.
POD-07	Pagination	Pagination spacing/alignment differs from Figma.	Match pagination layout and controls.
POD-08	Footer	Footer alignment and some text styling differ from the design.	Match footer layout and typography.
POD-09	Side navigation / UX	The current labeled side icons occupy space and can block links; the previous icon-only behavior with labels on hover was cleaner and easier to use.	Prefer compact icon-only navigation with hover labels, or otherwise ensure it never obstructs page links.



24. Check Title, img, and largest digital box color in all podcasts



25. The side icons look more user friendly and clean previously used, like their icons were just showing and on hover just give the name for the respective icon name. When these are as they are right now and according to design, many options, links become unable and not easy for the user to interact with.

5. Mobile QA Findings


Mobile View - General / About / What We Do / Ideas Lab

ID	Category	Finding	Required correction
MOB-01	Home	Home-page mobile issues are the same as those already documented in the desktop/home sections.	Apply the earlier responsive fixes.
MOB-02	About Us	Key Stats cards require sizing/placement changes; Vision & Mission visuals overlap or sit too close to text.	Reflow cards and prevent decorative-image overlap.
MOB-03	What We Do	Only the first page/section was available in the tested mobile view; remaining content was unavailable.	Ensure all What We Do sections are reachable/rendered on mobile.
MOB-04	Ideas Lab	Large empty space appears above the hero content.	Use/fill the area so the hero does not look incomplete.

Mobile View :

Home Page: Mentioned previously in pdf for this page.

About Us Page:



What We Do Page: Only one page of this landing page is available. Remaining pages unavailable.


Ideas Lab Page:




Mobile View - Grow With Us & Insights

ID	Category	Finding	Required correction
MOB-05	Grow With Us	Outcome illustrations/text overlap in mobile cards.	Reflow card content so artwork and text do not collide.
MOB-06	Grow With Us	Image/copy layout needs better spacing and alignment.	Use a mobile-specific stacked layout with consistent margins.
MOB-07	Insights filters	Filter dropdown sizing/position needs correction.	Size and place dropdown appropriately for mobile.
MOB-08	Insights header controls	Category filter, CTA buttons and message icon need more separation/alignment.	Increase spacing and align controls without crowding.

Grow With Us Page :



Insights By People First Page:




6. Tablet QA Findings

Tablet View - Home

ID	Category	Finding	Required correction
TAB-01	Tech Events	Text/stats are not aligned with the image as intended.	Correct tablet alignment and spacing.
TAB-02	Cards	Card dimensions/layout require adjustment for tablet.	Use a balanced tablet grid and consistent gaps.
TAB-03	Ecosystem	Decorative marks may need removal or slight repositioning at tablet width.	Tune decorative graphics for the tablet breakpoint.

Tablet View:

Home Page:



Tablet View - About, What We Do, Podcast, Grow With Us

ID	Category	Finding	Required correction
TAB-04	About Us	Journey card bullets/lines and CTA alignment require a consistent single-line treatment.	Fix internal card alignment and button positioning.
TAB-05	About Us - Stats	Stats card spacing/placement is inconsistent.	Rebalance the stat cards.
TAB-06	What We Do	Only the first page/section was available.	Ensure the full page is available on tablet.
TAB-07	Podcast	Images are partially hidden/clipped.	Prevent clipping and use responsive image sizing.
TAB-08	Grow With Us	Images are partially hidden/clipped.	Prevent clipping and preserve image visibility.

About Us Page:




What We Do Page : First page available.

Podcast Page:




Grow With Us Page:



Tablet View - Grow With Us / Insights

ID	Category	Finding	Required correction
TAB-09	Grow With Us	Card grid could make better use of center space; card arrangement needs refinement.	Use a balanced tablet grid.
TAB-10	Insights filters	Filter dropdown font size is too large.	Reduce font size for tablet.
TAB-11	Insights page	Additional text elements also need smaller font sizing.	Scale typography consistently for the breakpoint.



Insights by People First Page :



Fontsize should be small

7. Cross-Cutting Remediation Checklist

Area	Acceptance check
Typography	Confirm one approved font family system and apply the exact Figma size, weight, line height and letter spacing per breakpoint.
Spacing & alignment	Standardize section margins, card gaps, CTA spacing, footer columns and vertical rhythm.
Visual styling	Match Figma colors, gradients, shadows, borders, radii and decorative assets.
Images & icons	Use the correct source assets, aspect ratios, crop behavior and icon set; prevent clipping/overlap.
Responsive behavior	Test key breakpoints around small mobile widths (including ~568 px), standard mobile, tablet and desktop.
Floating navigation	Keep side navigation compact and non-obstructive; verify all links remain clickable at every breakpoint.
Forms	Add input length/format validation, clear user feedback, and consistent browser autofill styling.
Content availability	Verify that every section of long pages such as What We Do renders and remains reachable on mobile/tablet.

8. Recommended Verification Before Sign-Off

- Run a side-by-side visual comparison against Figma for every section after fixes are merged.
- Check desktop, tablet and multiple mobile widths, including the widths where overlap was previously observed.
- Confirm no text, decorative artwork, images or floating navigation overlap interactive controls.
- Test form validation for empty values, invalid email, letters in phone fields, long input values and browser autofill.
- Check footer and side-navigation interactions on every page, not only the Home page.
- Complete a final regression pass on all pages after typography and global spacing changes because those fixes can affect many sections at once.

END OF REPORT