

Fecha: 27/02/2026

Proyecto: Entrega Proyecto Final – DemoGuru99

Tester: Edgar Jonathan Vargas


Herramienta usada: Lighthouse

Sitio web: [demo.guru99.com/test/newtours/register.php]

PRUEBA DE ESTRES

Prueba 1 – Desktop

Performance - Rendimiento



INSIGHTS

- ▲ Use efficient cache lifetimes — Est savings of 238 KiB ▼
- ▲ Render blocking requests — Est savings of 300 ms ▼
- ▲ LCP request discovery ▼
- ▲ Network dependency tree ▼
- Font display — Est savings of 20 ms ▼
- Improve image delivery — Est savings of 112 KiB ▼
- Layout shift culprits ▼
- LCP breakdown ▼
- 3rd parties ▼

DIAGNOSTICS

- Image elements do not have explicit width and height ▼
- Minify CSS — Est savings of 4 KiB ▼
- Reduce unused CSS — Est savings of 19 KiB ▼
- Reduce unused JavaScript — Est savings of 133 KiB ▼

● Document request latency	▼
● Optimize DOM size	▼
● Duplicated JavaScript	▼
● Forced reflow	▼
○ INP breakdown	▼
● Legacy JavaScript	▼
● Modern HTTP	▼
● Optimize viewport for mobile	▼
● Minify JavaScript	▼
● Avoids enormous network payloads — Total size was 612 KiB	▼
○ User Timing marks and measures	▼
● JavaScript execution time — 0.0 s	▼
● Minimizes main-thread work — 0.3 s	▼
○ Avoid long main-thread tasks	▼
○ Avoid non-composited animations	▼
● Page didn't prevent back/forward cache restoration	▼

Accessability – Accesibilidad

Accessibility

These checks highlight opportunities to [improve the accessibility of your web app](#). Automatic detection can only detect a subset of issues and does not guarantee the accessibility of your web app, so [manual testing](#) is also encouraged.

NAMES AND LABELS

▲ Image elements do not have [a11y] attributes	▼
▲ Form elements do not have associated labels	▼
▲ Select elements do not have associated label elements.	▼
▲ Links do not have a discernible name	▼

These are opportunities to improve the semantics of the controls in your application. This may enhance the experience for users of assistive technology, like a screen reader.

CONTRAST

▲ Background and foreground colors do not have a sufficient contrast ratio.	▼
---	---

INTERNATIONALIZATION AND LOCALIZATION

- ▲ `<html>` element does not have a `[lang]` attribute

These are opportunities to improve the interpretation of your content by users in different locales.

BEST PRACTICES

- ▲ Touch targets do not have sufficient size or spacing.
- ▲ Document does not have a main landmark.
- Uses ARIA roles only on compatible elements
- Identical links have the same purpose.

These items highlight common accessibility best practices.

NAVIGATION

- The page contains a heading, skip link, or landmark region

PASSED AUDITS (9)

Hide

- `[aria-hidden="true"]` is not present on the document `<body>`
- `[role]`s have all required `[aria-*)` attributes
- `[role]` values are valid
- Input buttons have discernible text.
- Document has a `<title>` element
- Lists contain only `<li>` elements and script supporting elements (`<script>` and `<template>`).
- List items (`<li>`) are contained within `<ul>`, `<ol>` or `<menu>` parent elements
- Cells in a `<table>` element that use the `[headers]` attribute refer to table cells within the same table.
- Deprecated ARIA roles were not used

Best Practices - Buenas Practicas

50

Best Practices

TRUST AND SAFETY

- ▲ Does not use HTTPS — 1 insecure request found
- Ensure CSP is effective against XSS attacks
- Use a strong HSTS policy
- Ensure proper origin isolation with COOP
- Mitigate clickjacking with XFO or CSP
- Mitigate DOM-based XSS with Trusted Types

GENERAL

- ▲ Uses third-party cookies — 5 cookies found
- ▲ Browser errors were logged to the console
- ▲ Issues were logged in the **Issues** panel in Chrome Devtools
- Detected JavaScript libraries

BROWSER COMPATIBILITY

- ▲ Page lacks the HTML doctype, thus triggering quirks-mode Document must contain a doctype

PASSED AUDITS (8)

Hide

- Avoids deprecated APIs
- Allows users to paste into input fields
- Avoids requesting the geolocation permission on page load
- Avoids requesting the notification permission on page load
- Displays images with correct aspect ratio
- Serves images with appropriate resolution
- Properly defines charset
- Page has valid source maps

SEO



SEO

These checks ensure that your page is following basic search engine optimization advice. There are many additional factors Lighthouse does not score here that may affect your search ranking, including performance on [Core Web Vitals](#). [Learn more about Google Search Essentials](#).

CRAWLING AND INDEXING

- ▲ Page is blocked from indexing
- ! Links are crawlable — Error!

To appear in search results, crawlers need access to your app.

CONTENT BEST PRACTICES

- ▲ Document does not have a meta description
- ! Links have descriptive text — Error!
- ▲ Image elements do not have `[alt]` attributes

Format your HTML in a way that enables crawlers to better understand your app's content.

PASSED AUDITS (4) Hide

- Document has a `<title>` element
- Page has successful HTTP status code
- robots.txt is valid
- Document has a valid `hreflang`

Mas información sobre la prueba:

 Captured at Feb 25, 2026, 11:56 AM GMT-3

 Emulated Desktop with Lighthouse 13.0.1

 Single page session

 Initial page load

 Custom throttling

 Using Chromium 145.0.0.0 with devtools

Diagnostico - Desktop

Rendimiento

El sitio cumple con los estándares de velocidad más exigentes al presentar un puntaje de 97 sobre 100. Las métricas de carga como el LCP de 1.1 segundos y un TBT de 0 ms indican una respuesta inmediata para el usuario final. Sin embargo, existen observaciones menores en la gestión de caché y la eliminación de recursos que bloquean el renderizado que deben optimizarse para alcanzar la eficiencia total.

Accesibilidad

El estado actual es crítico con una puntuación de 53 sobre 100. Se han detectado defectos de prioridad alta por la falta de atributos alt en imágenes y la ausencia de etiquetas label en los elementos de formulario. Estas omisiones impiden que los usuarios con herramientas de asistencia puedan interactuar con la página, lo que representa un fallo de calidad en la experiencia de usuario inclusiva.

Buenas Prácticas


El sitio ofrece un desempeño deficiente de 50 sobre 100. El hallazgo más grave es la falta de un DOCTYPE definido, lo que fuerza al navegador a un modo de compatibilidad inestable. Adicionalmente, la presencia de solicitudes inseguras por no utilizar HTTPS de forma integral y los errores registrados en la consola del navegador comprometen la integridad técnica del sitio.

SEO

El módulo de SEO se encuentra en estado de error crítico. La página tiene configurada una directiva que bloquea la indexación, lo que significa que el producto no será visible en los motores de búsqueda. La falta de meta descripciones y de nombres discernibles en los enlaces son fallos estructurales que invalidan cualquier estrategia de posicionamiento orgánico.

Prueba 2 – Mobile

Performance – Rendimiento



INSIGHTS		
▲	Render blocking requests	— Est savings of 2,020 ms
▲	Use efficient cache lifetimes	— Est savings of 244 KiB
▲	Font display	— Est savings of 40 ms
▲	LCP request discovery	
▲	Network dependency tree	
■	Improve image delivery	— Est savings of 118 KiB
■	Optimize viewport for mobile	
○	Layout shift culprits	
○	LCP breakdown	
○	3rd parties	

DIAGNOSTICS

- Image elements do not have explicit `width` and `height` ▼
- Minify CSS — Est savings of 4 KiB ▼
- Reduce unused CSS — Est savings of 33 KiB ▼
- Reduce unused JavaScript — Est savings of 131 KiB ▼
- Avoid long main-thread tasks — 5 long tasks found ▼

PASSED AUDITS (14)

Hide

- Document request latency ▼
- Optimize DOM size ▼
- Duplicated JavaScript ▼
- Forced reflow ▼
- INP breakdown ▼
- Legacy JavaScript ▼
- Modern HTTP ▼
- Minify JavaScript ▼
- Avoids enormous network payloads — Total size was 618 KiB ▼
- User Timing marks and measures ▼
- JavaScript execution time — 0.4 s ▼
- Minimizes main-thread work — 1.3 s ▼
- Avoid non-composited animations ▼
- Page didn't prevent back/forward cache restoration ▼

Accessibility - Accesibilidad

53

Accessibility

These checks highlight opportunities to [improve the accessibility of your web app](#). Automatic detection can only detect a subset of issues and does not guarantee the accessibility of your web app, so [manual testing](#) is also encouraged.

NAMES AND LABELS

- ▲ Image elements do not have `[alt]` attributes
- ▲ Form elements do not have associated labels
- ▲ Select elements do not have associated label elements.
- ▲ Links do not have a discernible name

These are opportunities to improve the semantics of the controls in your application. This may enhance the experience for users of assistive technology, like a screen reader.

CONTRAST

- ▲ Background and foreground colors do not have a sufficient contrast ratio.

INTERNATIONALIZATION AND LOCALIZATION

- ▲ `<html>` element does not have a `[lang]` attribute

These are opportunities to improve the interpretation of your content by users in different locales.

BEST PRACTICES

- ▲ Touch targets do not have sufficient size or spacing.
- ▲ Document does not have a main landmark.
- Uses ARIA roles only on compatible elements
- Identical links have the same purpose.

These items highlight common accessibility best practices.

NAVIGATION

- The page contains a heading, skip link, or landmark region

PASSED AUDITS (9)	Hide
[aria-hidden="true"] is not present on the document <body>	▼
[role]s have all required [aria-*] attributes	▼
[role] values are valid	▼
Input buttons have discernible text.	▼
Document has a <title> element	▼
Lists contain only elements and script supporting elements (<script> and <template>).	▼
List items () are contained within , or <menu> parent elements	▼
Cells in a <table> element that use the [headers] attribute refer to table cells within the same table.	▼
Deprecated ARIA roles were not used	▼


Best Practices – Buenas Practicas

46 Best Practices	
TRUST AND SAFETY	
Does not use HTTPS — 1 insecure request found	▼
Ensure CSP is effective against XSS attacks	▼
Use a strong HSTS policy	▼
Ensure proper origin isolation with COOP	▼
Mitigate clickjacking with XFO or CSP	▼
Mitigate DOM-based XSS with Trusted Types	▼
GENERAL	
Uses third-party cookies — 4 cookies found	▼
Browser errors were logged to the console	▼
Issues were logged in the Issues panel in Chrome Devtools	▼
Detected JavaScript libraries	▼


USER EXPERIENCE	
▲ Serves images with low resolution	▼
BROWSER COMPATIBILITY	
▲ Page lacks the HTML doctype, thus triggering quirks-mode Document must contain a doctype	▼
PASSED AUDITS (7)	
	Hide
● Avoids deprecated APIs	▼
● Allows users to paste into input fields	▼
● Avoids requesting the geolocation permission on page load	▼
● Avoids requesting the notification permission on page load	▼
● Displays images with correct aspect ratio	▼
● Properly defines charset	▼
● Page has valid source maps	▼

SEO

! SEO These checks ensure that your page is following basic search engine optimization advice. There are many additional factors Lighthouse does not score here that may affect your search ranking, including performance on Core Web Vitals. Learn more about Google Search Essentials.	
CRAWLING AND INDEXING	
▲ Page is blocked from indexing	▼
! Links are crawlable — Error!	▼
To appear in search results, crawlers need access to your app.	
CONTENT BEST PRACTICES	
▲ Document does not have a meta description	▼
! Links have descriptive text — Error!	▼
▲ Image elements do not have [alt] attributes	▼



Mas información sobre la prueba:



Diagnostico - Mobile

Rendimiento

El puntaje de rendimiento en dispositivos móviles es de 71 sobre 100, lo que representa una caída significativa respecto a la versión de escritorio. El Largest Contentful Paint (LCP) se eleva a 5.3 segundos, entrando en un rango de carga lento que afecta la retención del usuario. Se han identificado bloqueos críticos por recursos que detienen el renderizado con un impacto de 2,020 ms y problemas en el descubrimiento de la solicitud LCP. Además, se detectaron 5 tareas largas en el hilo principal que degradan la interactividad en hardware móvil.

Accesibilidad

La puntuación se mantiene en un deficiente 53 sobre 100, evidenciando los mismos fallos estructurales que la versión desktop. Los elementos de imagen carecen de atributos alt y los formularios no cuentan con etiquetas label asociadas. Específicamente para mobile, los objetivos táctiles (botones y enlaces) no tienen el tamaño ni el espaciado suficiente, lo que dificulta la navegación táctil. El documento sigue omitiendo el atributo de idioma en la etiqueta html y carece de un landmark principal para la navegación de herramientas de asistencia.

Buenas Prácticas

El desempeño en esta categoría bajó a 46 sobre 100, señalando deficiencias graves en la salud técnica del sitio. Se mantiene el riesgo de seguridad por el uso de protocolos HTTP inseguros y la presencia de cookies de terceros. Un hallazgo crítico adicional en mobile es que el sitio sirve imágenes con baja resolución, lo que afecta negativamente la calidad visual. Persiste la falta de un DOCTYPE HTML, provocando que el sitio se ejecute en quirks-mode, y se registran múltiples errores de navegador en la consola.

SEO

El apartado de SEO continúa en estado de error crítico y no genera puntuación numérica. El sitio sigue bloqueado para la indexación de los motores de búsqueda, impidiendo cualquier visibilidad orgánica. Los enlaces no son rastreables y carecen de texto descriptivo, sumado a la ausencia total de una meta descripción en el documento. Aunque el archivo robots.txt y el hreflang son válidos, estos no compensan el bloqueo de indexación que actúa como un impedimento total para el despliegue en producción.