Loss Solutions Group, LLC
Toll Free 866.899.8756
Fax 860.639.5158
www.LossSolutionsGroup.com

February 23, 2026

Ms. Kate Raab
Travelers Insurance
PO Box 430
Buffalo, NY 14240

RE:	Insured:	LIQUID 8 TECHNOLOGY, INC.
	Claimant:	BROOKFIELD PROPERTIES NEW YORK
	Claim Number:	F8J0848
	LSG Matter Number:	787200.12801-00
	Date of Loss:	September 8, 2025

Dear Ms. Raab,

Thank you for choosing Loss Solutions Group as your equipment loss consultant. This report provides an analysis of the above-referenced claim.

Assignment:

Loss Solutions Group was contacted by Ms. Kate Raab of Travelers Insurance. The scope of this assignment was to assess the extent of damage and salvage value associated with the claimant's Secure USA-branded wedge-type barrier/security gate unit that sustained damage during a vehicle accident event on September 8, 2025.

Findings and Analysis:

Loss Solutions Group contacted the insured, Mr. Eugene Korzh with Liquid 8 Technology, Inc. (646-747-8437), to discuss our role in the claim. Mr. Korzh explained that one (1) of his truck drivers caused damage to the barrier when the driver was pulling out from the docking area, and that he did not know anything related to the repairs.

Loss Solutions Group contacted Ms. Zoe Norinski (212-618-2600), a tenant in the claimant's building (Brookfield Properties New York) to discuss our role in the claim. Ms. Norinski explained that she is a tenant in the building where the damage occurred. She had hired Liquid 8 Technologies to dispose of some of her computer equipment, and during their departure they damaged her building's security barrier. She mentioned that the building's management team took charge of communicating with the repair vendor and overseeing the repairs, for which she was billed. Lastly, she believes that the repairs have already been completed.

© 2022 by Loss Solutions Group, LLC. All rights reserved.

Loss Solutions Group contacted the claimant's mechanical repair vendor, D.M. Mechanical Services, Inc. (631-256-3055), and spoke with Mr. Michael P. to discuss the claimed event and their repairs. Mr. P. stated that he was one (1) of three (3) technicians who performed repairs on the security barrier that had been damaged by a vehicle. He noted that both the gearbox shaft of the gate's gearbox and the gate arm motor were damaged and needed to be replaced. Additionally, he explained that the parts replacement was completed by three (3) workers, and the total time taken for the repairs was seventy-two (72) hours. The vendor assisted us by providing the total sales tax amount for the repairs. When we requested a detailed breakdown of the materials and their costs needed for this repair, Mr. P. asked us to send him an email. We sent the initial email on January 23, 2026, followed by four (4) additional follow-up emails but received no response. We also made seven (7) additional calls in an attempt to speak with Mr. P. or anyone else who could provide the detailed breakdown of the parts used in this repair. Unfortunately, we were unsuccessful in obtaining further details from the vendor on the two (2) parts that were required and their costs.

A total amount of $31,737.06 was presented.

Scope of Damage

Loss Solutions Group submits that the claimant's building's Secure USA-branded wedge-type barrier/security gate unit sustained damage during a vehicle accident event on September 8, 2025.

Age & Condition

The vendor reported that the affected equipment was around ten (10) years old and in average condition at the time of the claimed event.

Cost Analysis

Loss Solutions Group assessed the proposed costs by cross-referencing with alternative vendors, drawing on historical data for similar repairs, evaluating comparable equipment pricing, and consulting directly with the involved vendor to verify reasonableness.

D.M. MECHANICAL SERVICES, INC. (631-256-3055) PROPOSAL # 25286

Loss Solutions Group reviewed the proposal presented by D.M. Mechanical totaling $31,737.06 for the repairs to the security gate/barrier.

Included in the cost is an amount for a gearbox and shaft assembly, a 1/3 horsepower Leeson-branded gate arm motor, and some cosmetic materials (paint and Bondo). We submit that these components were required to complete the repair.

Loss Solutions Group has reviewed the labor costs for the vendor to diagnose the damage and to perform the repair. We submit that these amounts are fair and reasonable to complete the scope of work as presented to us.

© 2022 by Loss Solutions Group, LLC. All rights reserved.

Note: A difference was noted between the claim cost and Loss Solutions Group's researched cost, totaling $11,883.81. This discrepancy is due to significantly higher material costs than what we were able to find online. For the first item, the "Gearbox and shaft," we contacted the manufacturer, Secure USA, and confirmed the cost of this assembly is $1,273.13. Regarding the second item, the "Gate arm motor," Loss Solutions Group was provided with a photograph of the motor's nameplate, where we found an identical motor listed on Grainger for $561.77.

Alternate Vendor Contacts

Further research in establishing valuation utilizing third-party vendors is discussed below:

Secure USA (201-568-1906)

Loss Solutions Group contacted Secure USA and spoke with Ms. Leila Birkenhead to help in gathering the cost of a replacement gearbox and shaft assembly. Ms. Birkenhead requested that we email her (leila.birkenhead@praesidiad.com) with photographs of their unit so that she could ensure it was the correct assembly. We sent Ms. Birkenhead an email with the details of the damages, and she provided us with an email with the cost of the assembly, stating that it would cost $1,273.13.

RCV

Loss Solutions Group submits an amount of $19,853.25 (RCV) as being fair and reasonable to return the equipment to a pre-loss condition. A further breakdown of the pricing is available in the attached spreadsheet.

ACV

Loss Solutions Group submits an actual cash value (ACV) amount of $18,745.50 based on linear age depreciation of the materials only. We estimate the average life expectancy of the equipment to be around twenty (20) years.

Salvage

Loss Solutions Group submits that there is little to no salvage value associated with this claimed event.

Summary:

Loss Solutions Group's findings herein are based upon all information that was available at the time of this writing. The opinions are based upon reviewed documentation, interviews, research, experience, historical references, training and education.

© 2022 by Loss Solutions Group, LLC. All rights reserved.

1. The insured, Liquid 8 Technology Inc, damaged the claimant's building's Secure USA-branded wedge-type barrier/security gate unit during a vehicle accident event on September 8, 2025. A total amount of $31,737.06 was presented.

2. The vendor reported that the affected equipment was around ten (10) years old and in average condition at the time of the claimed event.

3. Loss Solutions Group submits an amount of $19,853.25 (RCV) as being fair and reasonable to return the equipment to a pre-loss condition. A further breakdown of the pricing is available in the attached spreadsheet.

    a. Note: A difference was noted between the claim cost and Loss Solutions Group's researched cost, totaling $11,883.81. This discrepancy is due to significantly higher material costs than what we were able to find online. For the first item, the "Gearbox and shaft," we contacted the manufacturer, Secure USA, and confirmed the cost of this assembly is $1,273.13. Regarding the second item, the "Gate arm motor," Loss Solutions Group was provided with a photograph of the motor's nameplate, where we found an identical motor listed on Grainger for $561.77.

4. Loss Solutions Group submits an ACV amount of $18,745.50 based on linear age depreciation of the materials only.

5. Loss Solutions Group submits that there is little to no salvage value associated with this claimed event.

If you have any questions or if you need any additional information, please feel free to contact Tanner Beuret at (866) 899-8756 ext. 755, or via email at tbeuret@losssolutionsgroup.com. Team Leader Nick Ramos can be reached at (866) 899-8756 ext. 724, or via email at nramos@losssolutionsgroup.com.

Best regards,

Tanner Beuret
Technical Consultant
Loss Solutions Group, LLC

© 2022 by Loss Solutions Group, LLC. All rights reserved.

INSURED: LIQUID 8 TECHNOLOGY, INC.
CLAIMANT: BROOKFIELD PROPERTIES NEW YORK
LSG MATTER #: 787200.12801-00
CLAIM #: F8J0848
DATE OF LOSS: 9/8/2025
CAUSE OF LOSS: VEHICLE ACCIDENTS

COLOR DENOTES PRICING DISCREPANCY

D.M. MECHANICAL SERVICES, INC. (631-256-3055) PROPOSAL # 25286

REF #	ITEM	CLAIM PRESENTED			LSG RESEARCHED RCV			AGE (YEARS)	USEFUL LIFE (YEARS)	ACV (MAX DEPRECIATION 75%)	DEPRECIATION	CONDITION	NOTES
		QTY	UNIT COST	TOTAL	QTY	UNIT COST	TOTAL						
1	LABOR FOR THREE TECHNICIANS FOR 24 HOURS EACH	72	$ 225.00	$ 16,200.00	72	$ 225.00	$ 16,200.00	N/A	N/A	$ 16,200.00	$ -	AVERAGE	LABOR FOR THREE TECHNICIANS FOR 24 HOURS EACH TOTALING TO 72 HOURS.
2	MATERIALS	1	$ 12,950.00	$ 12,950.00	0	$ -	$ -	N/A	N/A	$ -	$ -	AVERAGE	MATERIALS NEEDED TO REPAIR THE DAMAGED UNIT. THIS PRICE WAS GIVEN TO US IN A LUMP SUM COST. WITH HELP FROM THE VENDOR WE WERE ABLE TO BREAK THIS COST DOWN AS FOLLOWS.
3	GEARBOX AND SHAFT	0	$ -	$ -	1	$ 1,273.13	$ 1,273.13	10	20	$ 636.57	$ 636.57	AVERAGE	SECURE USA GEARBOX AND SHAFT ASSEMBLY
4	GATE ARM MOTOR	0	$ -	$ -	1	$ 561.77	$ 561.77	10	20	$ 280.89	$ 280.89	AVERAGE	GATE ARM MOTOR (LEESON BRANDED 1/3 HORSEPOWER MOTOR)
5	COSMETIC REPAIRS	0	$ -	$ -	1	$ 200.00	$ 200.00	10	20	$ 100.00	$ 100.00	AVERAGE	BONDO AND PAINT
SUB-TOTAL				**$ 29,150.00**			**$ 18,234.90**			**$ 17,217.45**	**$ 1,017.45**		
SALES TAX				$ 2,587.06			$ 1,618.35			$ 1,528.05	$ 90.30		
TOTAL				**$ 31,737.06**			**$ 19,853.25**			**$ 18,745.50**	**$ 1,107.75**		

TOTAL PRESENTED	**$ 31,737.06**
TOTAL RESEARCHED RCV	**$ 19,853.25**
TOTAL ACV	**$ 18,745.50**
TOTAL DEPRECIATION	**$ 1,107.75**

© 2022 by Loss Solutions Group, LLC. All rights reserved.

D.M. MECHANICAL SERVICES, INC.

Proposal #25286

September 15, 2025

Michael Sessito/ Property Manager
Brookfield Properties New York
1 Liberty Plaza
New York, NY 10006

RE: Barrier Repairs

Dear Mr. Sessito,

We are pleased to offer you our quotation for the following scope of work:

Responded to emergency service call on 9/9 that wedge barrier was struck by truck and not functioning properly.
Disassembled housing to inspect unit.
Upon inspection found broken gearbox shaft and gate arm motor. Also found visible damage to housing.
Re-installed housing and left barrier out of commission.
Supply labor and materials to remove and replace gear box assembly and gate arm motor.
Supply labor and materials to make cosmetic repairs as best possible to barrier housing.
Disassemble housing and set aside.
Disconnect gate arm motor and discard
Disconnect gearbox assembly and discard.
Supply and install new gear box assembly.
Supply and install new gate arm motor.
Straighten, Bondo and paint barrier housing as needed.
Run system to check for proper operation. Any other defects found will be reported back to customer for additional repairs.
All work to be performed on regular business hours by OSHA approved personnel.
Note: Should scope of work change or increase (i.e., stand-by time, work hold-ups beyond our control, additional work, etc.) additional charges will be communicated to costumer for approval.
Exclusions:
Permits, Filings, Drawings
Overtime

Labor: 3 technicians 24 hours @ $225.00 / hr = $16,200.00
Materials: $12,950.00

PRICE: $29,150.00 plus any applicable taxes.
*Price valid for 30 days

261-4 Skidmore's Road Deer Park, NY 11729 (631) 256-3055

SecureUSA, Inc.
www.SecureUSA.net
BASEMENT
TOTAL
DUNKIN


Orion
R2
CERTIFIED
AAA
NAID CERTIFIED
THIEMAN
50649-NA

Broadway
ONE WAY
PIZZA
SecureUSA
www.SecureUSA.net
DANGER

SecureUSA, Inc.
www.SecureUSA.net

LEESON
E49747 LR2025
CATALOG NO. 101769.00
MODEL NO. C4T17FC10B
CUST. PART NO.
DATE B23K
H.P. 1/3
ENCL. TEFC
FR S56C
NOT THERMALLY PROTECTED
R.P.M 1725
HZ. 60
PH. 3
VOLTS 208-230/460
F.L.A. 1.5-1.6/.8
S.F.A. 1.7-1.8/.9
S.F. 1.15
AMB. 40 °C
CODE M
EFF. 64.3
INS. B3
DUTY. CONT
DESIGN B
P.F. 61.1
LOW VOLTAGE
T4 T5 T6
T7 T8 T9
T1 T2 T3
LINE LINE LINE
HIGH VOLTAGE
T4 T5 T6
T7 T8 T9
T1 T2 T3
LINE LINE LINE
TO REVERSE ROTATION, INTERCHANGE ANY TWO LINE LEADS.
103014
LEESON ELECTRIC CORPORATION
GRAFTON, WISCONSIN 53024 - 0241
ASSEMBLED IN MEXICO
WARNING: FAILURE TO FOLLOW ALL SAFETY INFORMATION CAN RESULT IN SERIOUS PERSONAL INJURY OR DEATH. DISCONNECT ALL POWER BEFORE SERVICING. INSTALL AND GROUND PER LOCAL AND NATIONAL CODES CONSULT QUALIFIED PERSONNEL WITH ANY QUESTIONS.

CATALOG NO. 101769.00
MODEL NO. C4T17FC10B
CUST. PART NO.
DATE B23K
H.P. 1/3
ENCL. TEFC
FR S56C
NOT THERMALLY PROTECTED
LOW VOLTAGE
HIGH VOLTAGE
T4 T5 T6
T7 T8 T9
T1 T2 T3
LINE LINE LINE
T4 T5 T6
T7 T8 T9
T1 T2 T3
LINE LINE LINE
TO REVERSE ROTATION, INTERCHANGE
ANY TWO LINE LEADS.
103014
WARNING: FAILURE TO FOLLOW ALL SAFETY INF
SERIOUS PERSONAL INJURY OR DEAT
BEFORE SERVICING. INSTALL AND GROUND PER LOC
CONSULT QUALIFIED PERSONNEL WITH ANY QUEST

Re: Get a quote on parts for this repair.

Summarize

Today at 11:07 AM

Leila Birkenhead <leila.birkenhead@praesidiad.com>

To: Tanner Beuret; **Cc:** Artur Serowik

We don't sell just the motor for the gate arm. It comes as an assembly with the gearbox and shaft, $1273,13.

Leila Birkenhead
Office Coordinator, SecureUSA
Office: +1 (201) 568-1906
Mobile: +1 (551) 655-7438
Email: leila.birkenhead@praesidiad.com

Betafence USA | 9 Basin Drive Suite 180 | Kearny, NJ | 07032

BETAFENCE SECURE USA

betafence.com

Securing What Matters.

[illegible] praesidiad.com

From: Tanner Beuret <tbeuret@losssolutionsgroup.com>
Sent: Friday, February 13, 2026 1:39 PM
To: Leila Birkenhead <leila.birkenhead@praesidiad.com>
Cc: Artur Serowik <artur.serowik@praesidiad.com>
Subject: Re: Get a quote on parts for this repair.

I'm only interested in getting a price on this one part for insurance purposes. Can I get an MSRP on these parts? I don't need a formal quote, just the price of these parts.

1. GEARBOX SHAFT

= I couldn't find the exact match for this unit.

2. GATE ARM MOTOR

= Leeson branded, 3phase, 60hz, 1/3HP. For $562

Tanner

Loss Solutions Group

Tanner Beuret
Technical Consultant
Southern Region

LEESON General Purpose Motors: Totally Enclosed Air-Over, C-Face Mount, 1/3 HP, 1,725 Nameplate RPM

Item 798KJ1 Mfr. Model 101769.00

Web Price $561.77 / each

Qty 1 Add to Cart

Ship Pickup

Expected to arrive Thu. Feb 12.

Ship to 76180 | Change

Shipping Weight 15.235 lbs

Add to List

Product Image Feedback Compare

Product Details

Catalog Page N/A

Brand LEESON	NEMA Design B
Manufacturer Part Number 101769.00	Motor Enclosure Design Totally Enclosed Air-Over
Motor Application General Purpose	Motor Shaft Rotation Reversible
Phase Three	Motor Mounting Type C-Face
Motor Design Three-Phase	Motor Mounting Position Horizontal
HP 1/3	Motor Shaft Design NEMA 56
Nameplate RPM 1,725	Removable Base Permanently Lubricated
No. of Speeds 1	Motor Frame Material Steel
Voltage 208-230/460V AC	Shaft Dia. 5/8 in
Full Load Amps 1.5-1.6/0.80 A	Motor Bearings Ball
Frame 56C	Overall Length 9-11/16 in
Usable @ 208V Yes	Weight 16 lb
Hz 60 Hz	Nominal Efficiency 64.3 %
Motor Service Factor 1.15	Standards CSA; UL

Compliance & Restrictions

This item is restricted in certain states. View all states.

Documents

Technical Data Sheet

Alternate Products

LEESON General Purpose Motors: Totally Enclosed Fan Cooled, Universal Mount, 1/3 HP, 208-230/460V
Item 801V96

Compare

Web Price $569.64 / each

Ask Chat