


Technical Service Information

RENAULT MB1/MJ3 SPRAG ROTATION



FOR PROPER SPRAG ROTATION, IT SHOULD LOCK COUNTER CLOCKWISE AND FREEWHEEL CLOCKWISE.

Copyright © 2000 ATSG

88-31 Page 1 of 1