EXPLORATION TESTS REPORT

Author: Paweł Aksman

Document version: AC-280823

Date: 19.03.2024

Website: http://www.kabut-pszow.pl/

Test environment:

Machine name	DESKTOP-7SD26JU
Machine Id	{09900EE7-E659-4FCD-A20F-74C087C1F07F}
Operating System	Windows 10 Home 64-bit (10.0, Build 19045) (19041.vb_release.191206-1406)
Language	Polish (Regional Setting: Polish)
System Manufacturer	HP
System Model	HP 250 G4 Notebook PC
BIOS	F.24 (type: UEFI)
Processor	Intel(R) Pentium(R) CPU N3700 @ 1.60GHz (4 CPUs), ~1.6GHz
Memory	4096MB RAM
Available OS Memory	3938MB RAM
Page File	5070MB used, 4756MB available
Windows Dir	C:\Windows
DirectX Version	DirectX 12
DX Setup Parameters	Not found
User DPI Setting	96 DPI (100 percent)
System DPI Setting	96 DPI (100 percent)
DWM DPI Scaling	Disabled
Miracast	Available, with HDCP
Microsoft Graphics Hybrid	Not Supported
DirectX Database Version	1.0.8
DxDiag Version	10.00.19041.2075 64bit Unicode
Browser	Google Chrome 122.0.6261.129

Session duration: 00:46:39

Preparing time: 00:03:00

Testing time: 00:32:39

Reporting time: 00:11:00

Idea:

- links
- · consistency of the user interface
 - o color
 - o font style
 - font size


Defects:

ID -01-

Incorrect selection of colors between font and background in the side menu:

required ratio: 4.5:1

• current ratio: 2.02:1




ID -02-

Incorrect selection of colors between font and background in the side menu:


required ratio: 4.5:1

• current ratio: 3.99:1



ID -03-

Lack of consistency in terms of fonts in the side menu



ID -04-

Lack of font consistency between the side menu and subpages: "o firmie", "kontakt", "dojazd", "formularz kontaktowy"



ID -05-

Too small font in the side menu and individual subpages

ID -6-

The page size is too small and does not take advantage of the content window size, making the text on the page difficult to view and read

ID -7-

Outdated website elements do not meet modern website development standards