



Dimension Mould JB 4730

3D View




Dimension Cavity




Repair Mould JB 4730


3D View



Before




After




Penutupan 2 Celah di Area Hijau
Penambahan 4 Celah di Area Kuning

Top View



Front View



Dimension

