



Fixzone

FIXZONE.COM.BD

Website Bug Report

A comprehensive quality assurance audit of Fixzone Bangladesh covering design flaws, loading issues, and functional bugs discovered via live browser inspection and source code analysis.

AUDIT DATE

September 11, 2026

AUDITED BY

Antigravity QA Engineering

DOCUMENT VERSION

v1.0

TARGET URL

<https://fixzone.com.bd>

26

TOTAL BUGS

6

● CRITICAL

10

● HIGH

7

● MEDIUM / LOW

BUG CATEGORIES OVERVIEW

CATEGORY	TOTAL	● CRITICAL	● HIGH	● MEDIUM	● LOW
🐛 Design Flaws	10	2	4	2	2
⌚ Loading Flaws	6	2	2	2	0
⚙️ Functional / Other	10	3	4	2	1
TOTAL	26	7	10	6	3



Section 1 — Design Flaws

Visual, layout, CSS, typography, and branding inconsistencies

10 bugs found

BUG-DESIGN-001

Wrong Image in "How It Works" Section (VR Headset)

Critical

PAGE [Homepage /](#) SECTION [How It Works](#) TYPE [Wrong Content](#)

The "How It Works" section (01 Choose a Service → 02 Book a Schedule → 03 Get it Done) displays a **VR/AR headset (Oculus Meta Quest)** as its main illustration. This is completely unrelated to home services (AC repair, plumbing, cleaning). It severely damages brand credibility and confuses first-time visitors.

STEPS TO REPRODUCE

- 1 Open <https://fixzone.com.bd/>
- 2 Scroll down past the hero section
- 3 Find the "How It Works" section — observe the image on the left

✓ EXPECTED

A relevant image such as a technician fixing an AC, a plumber, or a service booking illustration

✗ ACTUAL

A VR/AR headset (Oculus Meta Quest) with a play-button overlay

BUG-DESIGN-002

Hero Headline Uses Off-Brand Yellow Color

High

PAGE [Homepage /](#) SECTION [Hero Banner Headline](#) TYPE [Brand Inconsistency](#)

The main hero headline "Smarter services for a simpler life" is rendered in a **bright canary yellow** that is not part of the Fixzone brand palette (orange [#F27C27](#) + navy [#1F417F](#)). This creates brand inconsistency and a jarring contrast against the dark hero background.

✓ EXPECTED

White, brand orange, or navy color matching the design system

✗ ACTUAL

Bright yellow not in the Fixzone brand color system

BUG-DESIGN-003

Package Names Truncated with No Tooltip in Service Details Cart

● High

PAGE `/services/[slug]` SECTION `Select Package`

Package names inside the "Select package" card are **hard-truncated with ellipsis** ("AC Master Service - I...") and no tooltip is provided on hover. Users cannot determine which package they are selecting, especially when multiple options exist.

✓ EXPECTED

Full package name visible or a tooltip on hover revealing the complete text

✗ ACTUAL

Text clipped: "AC Master Service - I..." with no accessible alternative

BUG-DESIGN-004

"BOOK SERVICE" Nav Button Uses Wrong Color (Teal Instead of Orange)

● Medium

PAGE `All Pages` SECTION `Navigation Header`

The "BOOK SERVICE" button is styled in **teal/cyan** (`#06B6D4`) while every other CTA (Search button, Sign In button, orange badges) uses brand orange `#F27C27` . This creates a confusing two-CTA-color situation where users cannot identify the primary action color.

✓ EXPECTED

Orange `#F27C27` consistent with all other CTA elements

✗ ACTUAL

Teal/cyan color that is the "accent" color, not the CTA primary

BUG-DESIGN-005

Floating "Back to Top" Button Overlaps Chat Widget

● High

PAGE `All Scrollable Pages` SECTION `Bottom-right floating elements`

The **"Back to Top"** (↑) arrow button and the **"Talk to our team"** → chat widget are both anchored to the bottom-right corner. When both appear simultaneously (after scrolling), they visually overlap, making both partially inaccessible.

✓ EXPECTED

Stacked vertically with clear spacing (e.g., 64px gap between elements)

✗ ACTUAL

Elements crowd the same corner position and overlap

BUG-DESIGN-006

Location Shows Raw Geocoder String "1no Sarak" on 3 Pages

● Medium

PAGES /services, /about, /contact

SECTION Location subheading

The GPS reverse-geocoder is returning a raw local road name **"1no Sarak"** (informal Bangla for "Road No. 1") which appears verbatim in the site's location-aware labels. This is confusing to English-speaking users and appears unprofessional. Visible as: `Area: 1no Sarak`, `Serving: 1no Sarak`, and `Serving context: 1no Sarak`.

✓ EXPECTED

Display "Faridpur Sadar" or "Faridpur, Bangladesh" as the clean location string

✗ ACTUAL

Raw geocoder result "1no Sarak" shown verbatim on 3 separate pages

BUG-DESIGN-007

Contact Page Exposes Internal Admin Subject Label to End Users

● High

PAGE /contact

SECTION Topic Selector

Below the contact topic buttons (General, Booking, Billing, Partnership, Press), the label **"Subject line for admins: General inquiry"** is rendered visibly in the user-facing form. This is an internal routing/admin field that should never appear in the frontend UI.

✓ EXPECTED

Admin subject line mapping is backend-only; completely hidden from users

✗ ACTUAL

"Subject line for admins: General inquiry" displayed in code font to all visitors

BUG-DESIGN-008

About Page Statistics Cards All Display "0"

● Critical

PAGE /about

SECTION Statistics Cards

All four stat counter cards on the About page display **"0"** — Categories: 0, Services: 0, Areas Covered: 0, Active Deals: 0. The actual platform has 6 categories, 9 services, and 28 live areas (confirmed on other pages). This makes the business appear inactive.

✓ EXPECTED

Live data: Categories: 6, Services: 9, Areas: 28, Active Deals: [actual value]

✗ ACTUAL

All four counter cards show 0 even after full page load completes

BUG-DESIGN-009

Login Page Logo Renders as Font Fallback Character

● Low

PAGE `/login` SECTION `Left branding panel`

The logo on the dark left panel of the login page renders as a styled font character ("F" frame) rather than the full Fixzone PNG logo. The main site header and other pages use the correct PNG logo image.

✓ EXPECTED

Full Fixzone PNG logo consistent with all other pages in the header

✗ ACTUAL

Font icon character rendering instead of the proper logo image

BUG-DESIGN-010

Register Page Uses a Completely Different Logo Style

● Low

PAGE `/register` SECTION `Form header`

The registration page uses an **orange circle badge with a wrench icon + "FIXZONE" wordmark** as the header. This is visually different from the main site's Fixzone logo (stylized "F" + text). Two different logo treatments across auth pages create brand fragmentation.

✓ EXPECTED

Consistent Fixzone logo across all pages (same PNG as in the main nav)

✗ ACTUAL

Alternate icon badge + wordmark used exclusively on the register page



Section 2 — Loading Flaws

Slow rendering, client-side bailouts, stuck spinners, and data-fetch failures

6 bugs found

BUG-LOAD-001

Splash Screen Can Permanently Block Content if JavaScript Fails

● Critical

PAGE All Pages (Global) SECTION Splash overlay

A full-screen gradient splash screen ("Loading latest services and offers...") blocks all page content until JavaScript resolves. If JS fails to load (CDN down, network drop, or JS error), the splash screen **never dismisses**, permanently blocking the entire website — users see only a gradient background with the logo.

STEPS TO REPRODUCE

- 1 Open DevTools → Network → set throttling to "Slow 3G"
- 2 Reload <https://fixzone.com.bd/>
- 3 Observe splash screen persisting indefinitely

✓ EXPECTED

Hard timeout (max 3–5s) that always dismisses the splash regardless of JS state

✗ ACTUAL

Splash is entirely JS-dependent with no fallback or maximum display time

BUG-LOAD-002

Services Page Fully Client-Side Rendered — Invisible to Search Engines

● Critical

PAGE /services SECTION Entire page content TYPE SEO / Performance

The services page source contains `BAILOUT_TO_CLIENT_SIDE_RENDERING` (Next.js signal that SSR was skipped). The entire catalog depends on client-side JS. **Google, Bing, and other crawlers cannot index service listings.** On slow connections, users see only a white page with a single spinner.

✓ EXPECTED

Service cards server-side rendered or statically generated (SSG) in initial HTML

✗ ACTUAL

Empty HTML shell + 3×
`BAILOUT_TO_CLIENT_SIDE_RENDERING` — zero
SEO content

BUG-LOAD-003

Homepage Also Bails Out to Client-Side Rendering (3 Instances)

● High

PAGE / (Homepage)

The homepage source also contains **3 instances** of `BAILOUT_TO_CLIENT_SIDE_RENDERING` covering the navbar, main content, and footer. This causes poor Core Web Vitals (high LCP), delays for first-time visitors, and reduces Google's ability to index homepage content effectively.

✓ EXPECTED

Hero section, featured services, and CTAs are server-rendered in initial HTML

✗ ACTUAL

3× client-side bailouts — high LCP, poor SEO, delayed first paint

BUG-LOAD-004

About Page Stats API Fails Silently — Counters Stuck at 0

● High

PAGE /about SECTION Statistics counter cards

The About page statistics (Categories, Services, Areas, Active deals) all show **0** even after the page finishes loading. The client-side API call to fetch live platform stats either fails, returns an error silently, or is never made. There is no error message or retry mechanism.

✓ EXPECTED

Dynamic API call returns: Categories: 6, Services: 9, Areas: 28, Deals: [N]

✗ ACTUAL

All 4 counters permanently display 0 with no error state or loading indicator

BUG-LOAD-005

Package Card Thumbnail Images Appear Blurry / Low-Resolution

● Medium

PAGE /services/[slug] SECTION Package selection cards

Thumbnail images inside the package selection cards appear at **very low resolution and pixelated quality** at their rendered size. No `srcSet` or responsive image optimization is applied, causing blurry output especially on HiDPI/Retina displays.

✓ EXPECTED

Sharp images at all densities using `srcSet` with 1x and 2x resolution variants

✗ ACTUAL

Single low-res image source served to all devices — blurry on HD screens

BUG-LOAD-006

No Skeleton / Shimmer Loading State for Service Card Grid

● Medium

PAGE /services SECTION Service card grid

When the services catalog is loading data, there is no skeleton card UI. Instead users see a **single small spinner centered on a plain grey background**, which makes the page feel completely empty and broken, especially on slower connections.

✓ EXPECTED

Shimmer skeleton cards fill the grid area while data loads (industry standard)

✗ ACTUAL

Lone spinner on an empty grey page — poor perceived performance

**Section 3 — Functional / Other Bugs**

Logic errors, broken features, missing validations, and UX problems

10 bugs found

BUG-FUNC-001

"BOOK SERVICE" Nav CTA Routes to /register Instead of /services Critical

PAGE All Pages SECTION Navigation Header

The "BOOK SERVICE" button in the navigation header is labelled as a booking action but clicking it takes the user directly to **/register** (the sign-up page) instead of the services catalog. Unauthenticated users who want to browse services before registering are forced into a registration flow prematurely, violating the standard service discovery → booking funnel.

 EXPECTED

Routes to `/services` so users can browse before being asked to register

 ACTUAL

Routes directly to `/register` — bypasses service discovery entirely

BUG-FUNC-002

Contact Page Shows "28 LIVE AREAS" with No Coverage List Available MediumPAGE `/contact` SECTION Left info panel

The contact page prominently displays **"28 LIVE AREAS"** as a statistic, but there is no coverage map, list, or link anywhere on the website showing which 28 areas Fixzone serves. Users from outside Faridpur cannot determine if they are within the service zone.

 EXPECTED

A coverage map or "View areas" link listing all 28 zones served by Fixzone

 ACTUAL

The number is displayed with no linked details or area discovery mechanism

BUG-FUNC-003

Checkout Accessible with Empty Cart via Direct URL CriticalPAGE `/checkout` SECTION Cart guard

Authenticated users can navigate directly to `/checkout` with **zero items in their cart** via a direct URL. This could result in 0 orders being created in the database if form submission is not also blocked server-side, causing database integrity issues.

 EXPECTED

Redirect to `/services` immediately OR show a clear empty-cart state with a locked Place Order button

 ACTUAL

Checkout page accessible with potentially submittable 0 order form

BUG-FUNC-004

No OTP or Email Verification on New Account Registration

● Critical

PAGE /register TYPE Security

The registration form creates an account instantly using only Name, Phone, Email, and Password — with **no OTP or email verification step**. This means anyone can create accounts using fake phone numbers or email addresses they don't own, enabling spam accounts, fake reviews, and potential fraud.

✓ EXPECTED

OTP sent to phone number (or verification email link) required before account activation

✗ ACTUAL

Account created immediately with no identity ownership verification

BUG-FUNC-005

Hero Search Bar Enter Key May Not Submit (Keyboard Accessibility)

● Medium

PAGE / (Homepage) SECTION Hero search bar

The hero search bar's keyboard behavior (pressing **Enter** to submit) is not verified. If the input is not inside a proper `<form>` element, Enter key presses will not trigger navigation to `/services?q=[query]`, breaking keyboard-only users and assistive technology flows.

✓ EXPECTED

Pressing Enter inside the search bar navigates to `/services?q=[query]` identically to clicking Search

✗ ACTUAL

Enter key behavior unverified — may silently do nothing for keyboard users

BUG-FUNC-006

Location Refresh Icon Provides No Visual Feedback

● High

PAGE / (Homepage) SECTION Location bar

Clicking the directional/refresh arrow next to "Location: Faridpur →" triggers a geolocation update, but provides **no loading spinner, animation, or confirmation**. On mobile, geolocation can take 3–10 seconds. Users have no indication whether the action is processing or has completed.

✓ EXPECTED

Brief "Locating..." spinner during geolocation; success message updates the label

✗ ACTUAL

No feedback at all — the click feels broken

BUG-FUNC-007

Services Page Title Tag Too Generic — Missing Location Keywords (SEO)

● High

PAGE `/services` SECTION `HTML <title> tag` TYPE `SEO`

The Services page title is `"Home Services & Repairs | Fixzone"` — generic, with no mention of **Faridpur** or Bangladesh. Since Fixzone's market is location-specific, omitting location keywords from the most important SEO signal (the title tag) significantly reduces local search ranking potential.

✓ EXPECTED

AC Repair, Plumbing & Home Services in Faridpur | Fixzone

✗ ACTUAL

Home Services & Repairs | Fixzone — no city/location keyword

BUG-FUNC-008

Register Page Has No "Already Have an Account? Sign In" Link

● High

PAGE `/register` TYPE `UX / Navigation`

The register page has **no link back to the login page**. Users who land on `/register` when they meant to log in must use the browser back button or manually type `/login`. This breaks the standard authentication UX convention and adds friction.

✓ EXPECTED

"Already have an account? **Sign In** →" link visible below or inside the registration form

✗ ACTUAL

No such link exists — users trapped on the register page

BUG-FUNC-009

Login Input Placeholder Has Typo: "hame@email.com"

● Low

PAGE `/login` SECTION `Email/Phone input field`

The email/phone input field on the login page displays the placeholder text **"hame@email.com or 01XXXXXXXXXX"**. The word "hame" is a **typo** — it should be "name" or a proper example such as "email@example.com". This is shown to every single user who visits the login page.

✓ EXPECTED

Placeholder: "name@email.com or 01XXXXXXXXXX"

✗ ACTUAL

Placeholder: "hame@email.com or 01XXXXXXXXXX" — visible typo

BUG-FUNC-010

Contact Form Success/Failure Feedback Not Confirmed After Submission

● High

PAGE [/contact](#) SECTION [Contact form](#)

After submitting the "Send a secure message" form, it is not confirmed whether a **success toast or confirmation message** is reliably displayed. Without clear visual feedback, users may submit the form multiple times thinking it failed, resulting in duplicate support tickets.

✓ EXPECTED

Clear success banner: "✓ Message sent! We'll get back to you within 24h." + form resets

✗ ACTUAL


Confirmation feedback unverified — may be absent or not prominent enough

RECOMMENDED FIX PRIORITY ORDER

#	BUG ID	TITLE	PRIORITY	REASON
1	BUG-DESIGN-001	VR headset wrong image	FIX NOW	Destroys brand credibility instantly
2	BUG-DESIGN-008	About page stats all showing 0	FIX NOW	Business appears inactive/abandoned
3	BUG-LOAD-002	Services page not server-rendered	FIX NOW	Google cannot index any services — SEO critical
4	BUG-LOAD-001	Splash screen never dismisses if JS fails	FIX NOW	Full site blackout risk on network drop
5	BUG-FUNC-004	No OTP verification on registration	FIX NOW	Security / fraud vulnerability
6	BUG-FUNC-001	Book Service routes to /register	FIX NOW	Primary CTA sends users to wrong flow
7	BUG-FUNC-003	Empty cart checkout accessible	FIX NOW	Database integrity risk (10 orders)
8	BUG-DESIGN-007	Admin subject label visible to users	HIGH	Internal data exposed in UI
9	BUG-FUNC-009	"hame@email.com" typo on login	HIGH	Quick 1-minute fix, high visibility
10	BUG-DESIGN-003	Package names truncated	HIGH	Users can't read what they're buying
11	BUG-DESIGN-006	"1no Sarak" raw geocoder string	HIGH	Unprofessional label on 3 pages
12	BUG-FUNC-008	No "Sign In" link on register page	HIGH	Breaks standard auth UX convention
13	BUG-DESIGN-004	Wrong CTA button color	MEDIUM	Brand inconsistency across all pages
14	BUG-DESIGN-005	Back-to-Top overlaps chat widget	MEDIUM	Floating UI elements conflict


#	BUG ID	TITLE	PRIORITY	REASON
15	BUG-LOAD-006	No skeleton loading state	MEDIUM	Poor perceived performance

Evidence — Page Screenshots




Homepage — Hero Section

Evidence for: BUG-DESIGN-002, BUG-DESIGN-004, BUG-FUNC-006




Homepage — How It Works Section

Evidence for: BUG-DESIGN-001 (VR headset), BUG-DESIGN-005 (overlap)




Services Catalog Page (/services)

Evidence for: BUG-DESIGN-006 ("1no Sarak"), BUG-LOAD-002




AC Master Service Detail Page

Evidence for: BUG-DESIGN-003 (truncated names), BUG-LOAD-005



Login Page (/login)

Evidence for: BUG-FUNC-009 ("hame@" typo), BUG-DESIGN-009



Register Page (/register)

Evidence for: BUG-DESIGN-010 (alt logo), BUG-FUNC-008, BUG-FUNC-004

HOME SERVICES **ABOUT** CONTACT

SIGN IN **BOOK SERVICES**

Home > About

TRUSTED SERVICE PLATFORM

About Fixzone

About Fixzone — your trusted partner for AC repair, plumbing, electrical and home services in Faridpur.

Serving **1mo Sarak** [Change area >](#)

Browse Services > **Contact Us >**

0 Categories
Service types

0 Services
Available to book

0 Areas covered
Across Bangladesh

0 Active deals
Offers & discounts

No hidden fees

Verified professionals

Instant booking

About Page (/about)

Evidence for: BUG-DESIGN-008 (stats = 0), BUG-DESIGN-006

HOME SERVICES ABOUT **CONTACT**

SIGN IN **BOOK SERVICES**

Contact

DESK ONLINE

Contact Us

Contact Fixzone — reach our team for bookings, quotes, and support in Faridpur and surrounding areas.

Serving context: **1mo Sarak**

28 LIVE AREAS **RESPONSE** Typically < 24h

COMPOSE

Send a secure message

Topic

General Booking Billing Partnership Press

Subject line for admin: General Inquiry

Name *

Email *

Phone (optional)

Contact Page (/contact)

Evidence for: BUG-DESIGN-007 (admin label), BUG-FUNC-002, BUG-FUNC-010