



Apparel Inspection Report

Origin / Division	BD / Apparel	QC Stage	Puma Warehouse
Factory	TBDAG	Sample Size Mode	WH AQL
Inspector Name	PQC Mahadi Hasan	Inspection Date	14 Jan 2026
Inspector Email	kuwa-65@kuwatechno.com	GPS (accuracy)	23°57'08.5"N 90°36'55.2"E (40m)
		Warehouse Location	

PO #	LCHD	Sales Subsidiary	Final Customer	Inspected
------	------	------------------	----------------	-----------

1.	4602757531	25 Jan 2026	JPPUJ	☒
2.	4602757536	25 Jan 2026	JPPUJ	☒

Description	Style	Color	Size	PO Qty	Actual Qty	PF	Pick Cartons	Sample Size
-------------	-------	-------	------	--------	------------	----	--------------	-------------

1.	ACTIVE SPORTS AOP Shorts Set B	680317	14	128	569	569	60	3	26 Adjust...
2.	ACTIVE SPORTS AOP Shorts Set B	680317	14	140	683	683	60	4	31 Adjust...
3.	ACTIVE SPORTS AOP Shorts Set B	680317	14	152	665	665	60	3	30 Adjust...
4.	ACTIVE SPORTS AOP Shorts Set B	680317	14	164	483	483	60	3	22 Adjust...
5.	ACTIVE SPORTS AOP Shorts Set B	680317	01	128	423	423	60	2	19 Adjust...
6.	ACTIVE SPORTS AOP Shorts Set B	680317	01	140	554	554	60	3	25 Adjust...
7.	ACTIVE SPORTS AOP Shorts Set B	680317	01	152	595	595	60	3	27 Adjust...
8.	ACTIVE SPORTS AOP Shorts Set B	680317	01	164	428	428	60	2	20

Total				4400	4400		23	200
-------	--	--	--	------	------	--	----	-----

Preparation

The following documents should be available for inspection:

- Packing List
- Puma’s Packaging and Labelling Manual
- Vendor's Internal Final Inspection Report

- Tech Pack
- Shipping and Special Instructions

Results	Double Sampling	Status	Defects Found	
			Major	Minor
1. Measurement & Fitting		Pass	0	
2. Workmanship		Pass	3 / 10	0 / 14
3. Packaging & Labelling	☐			
Overall Result		Pass		
Comments / Required Actions				

Measurement & Fitting		Pass		
			Round 1	Round 2
Total Defects Found			0	
Completed			☒	☐
680317 - 14 - 128	Sample Size		2	
	Defects Found		0	
680317 - 14 - 140	Sample Size		2	
	Defects Found		0	
680317 - 14 - 152	Sample Size		2	
	Defects Found		0	
680317 - 14 - 164	Sample Size		2	
	Defects Found		0	
680317 - 01 - 128	Sample Size		2	
	Defects Found		0	
680317 - 01 - 140	Sample Size		2	
	Defects Found		0	
680317 - 01 - 152	Sample Size		2	
	Defects Found		0	
680317 - 01 - 164	Sample Size		2	
	Defects Found		0	

Sample Size	200		Major	Minor
Completed	☒	Total Defects Found	3	0

A.	Componentry & Trims	Defects Found	0	0
B.	Fabric	Defects Found	1	0

Fabric Performance

Pilling / shedding / snagging

Major

Minor

680317 - 01 - 152

1

0

Pull yarn.



Minor

A

C.	Finishing & Pressing	Defects Found	0	0
D.	Logo & Embellishment	Defects Found	0	0
E.	Safety	Defects Found	0	0
F.	Sewing & Linking	Defects Found	1	0

Workmanship

Others - Workmanship

Major


Minor

680317 - 14 - 140

1

0

Asymmetric side seam length.



Major A

G.	Trimming & Threads	Defects Found	0	0
H.	Packaging & Labelling	Defects Found	1	0

Sticker / Label

Others - Sticker/ Label	Major	Minor
680317 - 01 - 140	1	0

Care label letter print colour migration.



Major C