



Apparel Inspection Report

Origin / Division	BD / Apparel	QC Stage	Puma Warehouse
Factory	TBDAG	Sample Size Mode	WH AQL
Inspector Name	PQC Mahadi Hasan	Inspection Date	14 Jan 2026
Inspector Email	kuwa-65@kuwatechno.com	GPS (accuracy)	23°57'08.4"N 90°36'55.2"E (40m)
		Warehouse Location	

PO #	LCHD	Sales Subsidiary	Final Customer	Inspected
1. 4602717953	15 Jan 2026	JPPUJ		☒
2. 4602717941	15 Jan 2026	JPPUJ		☒
3. 4602717901	15 Jan 2026	JPPUJ		☒
4. 4602717948	15 Jan 2026	JPPUJ		☒

Description	Style	Color	Size	PO Qty	Actual Qty	PF	Pick Cartons	Sample Size
1. ACTIVE SPORTS Small Graphic Tee B	529075	50	130	97	97	80	1	5
2. ACTIVE SPORTS Small Graphic Tee B	529075	50	140	290	290	80	2	12 Adjust...
3. ACTIVE SPORTS Small Graphic Tee B	529075	50	150	291	291	80	2	12 Adjust...
4. ACTIVE SPORTS Small Graphic Tee B	529075	50	160	290	290	80	2	12 Adjust...
5. ACTIVE SPORTS Small Graphic Tee B	529075	01	130	102	102	80	1	4 Adjust...
6. ACTIVE SPORTS Small Graphic Tee B	529075	01	140	313	313	80	2	13 Adjust...
7. ACTIVE SPORTS Small Graphic Tee B	529075	01	150	315	315	80	2	13 Adjust...
8. ACTIVE SPORTS Small Graphic Tee B	529075	01	160	315	315	80	2	13 Adjust...
9. ACTIVE SPORTS Small Graphic Tee B	529075	02	130	98	98	80	1	5
10. ACTIVE SPORTS Small Graphic Tee B	529075	02	140	293	293	80	2	12 Adjust...
11. ACTIVE SPORTS Small Graphic Tee B	529075	02	150	295	295	80	2	12 Adjust...

12.	ACTIVE SPORTS Small Graphic Tee B	529075	02	160	294	294	80	2	12 Adjust...
				Total	2993	2993		21	125

Preparation

The following documents should be available for inspection:


- Packing List
- Puma’s Packaging and Labelling Manual
- Tech Pack
- Vendor's Internal Final Inspection Report

- Shipping and Special Instructions

Results	Double Sampling	Status	Defects Found	
			Major	Minor
1. Measurement & Fitting		Pass	1	
2. Workmanship		Pass	1 / 7	0 / 10
3. Packaging & Labelling	☐			
Overall Result		Pass		
Comments / Required Actions				

		Round 1	Round 2
Total Defects Found		1	0
Completed		☒	☒
529075 - 50 - 130	Sample Size	2	
	Defects Found	0	
529075 - 50 - 140	Sample Size	2	
	Defects Found	0	
529075 - 50 - 150	Sample Size	2	
	Defects Found	0	
529075 - 50 - 160	Sample Size	2	
	Defects Found	0	
529075 - 01 - 130	Sample Size	2	3
	Defects Found	1	0
Measurements: off spec - exceeding tolerance		1	0
Back length minus (-1.8) cm			
			
529075 - 01 - 140	Sample Size	2	
	Defects Found	0	
529075 - 01 - 150	Sample Size	2	
	Defects Found	0	
529075 - 01 - 160	Sample Size	2	
	Defects Found	0	
529075 - 02 - 130	Sample Size	2	
	Defects Found	0	

529075 - 02 - 140	Sample Size	2
	Defects Found	0
529075 - 02 - 150	Sample Size	2
	Defects Found	0
529075 - 02 - 160	Sample Size	2
	Defects Found	0

Workmanship		Pass		
Sample Size	125		Major	Minor
Completed	☒	Total Defects Found	1	0
A.	Componentry & Trims	Defects Found	0	0
B.	Fabric	Defects Found	1	0
Yarn Defects				
Uneven yarn - slubs / thick - thin places / large knots			Major	Minor
529075 - 01 - 150			1	0
Slubs at front part area.				
				
Major		A		
C.	Finishing & Pressing	Defects Found	0	0
D.	Logo & Embellishment	Defects Found	0	0
E.	Safety	Defects Found	0	0
F.	Sewing & Linking	Defects Found	0	0
G.	Trimming & Threads	Defects Found	0	0
H.	Packaging & Labelling	Defects Found	0	0