


Crater report 3892 of RG5

General information



ID:3892

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter : $187m \pm 8.0m$

Mean depht : $12.0m \pm 0.7m$

d/D ratio : 0.064 ± 0.004

Circularity index: 0.93

Mean slope: 8.74

Geometric center coordinates: (3645203.548,

208648.4783)

Coordinates of the crater's lowest point :

(3645227.4999998994, 208632.49999999999)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	9.38	0.22
10°	8.53	0.21
20°	8.06	0.21
30°	7.94	0.2
40°	8.68	0.19
50°	8.92	0.19
60°	8.63	0.2
70°	8.59	0.2
80°	8.69	0.2
90°	9.22	0.21
100°	8.78	0.2
110°	8.43	0.19
120°	8.23	0.18






130°	8.08	0.17
140°	7.96	0.17
150°	7.37	0.17
160°	7.16	0.17
170°	7.46	0.18
180°	7.96	0.19
190°	8.02	0.18
200°	7.93	0.19
210°	8.07	0.18
220°	8.38	0.17
230°	9.03	0.17
240°	9.08	0.19
250°	8.73	0.18
260°	9.22	0.19
270°	10.0	0.2
280°	9.79	0.19
290°	9.72	0.19
300°	10.1	0.19
310°	10.49	0.17
320°	9.82	0.17
330°	9.62	0.18
340°	9.25	0.2
350°	9.22	0.21

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

