


# Crater report 696 of RG5

#### **General information**



**ID**:696

Study area: RG5 Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 251m ± 12.0m

Mean depht:  $10.0m \pm 0.6m$ 

d/D ratio : 0.04 ± 0.003 Circularity index : 0.94

Mean slope: 4.62

Geometric center coordinates: (3642876.887,

246638.0216)

**Coordinates of the crater's lowest point :** (3642897.4999999, 246627.4999999016)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.89	0.17
10°	4.78	0.17
20°	4.85	0.16
30°	4.92	0.15
40°	5.14	0.15
50°	5.47	0.15
60°	5.49	0.16
70°	5.64	0.16
80°	5.94	0.16
90°	6.06	0.17
100°	5.27	0.17
110°	4.86	0.16
120°	4.6	0.15






4.78	0.14
4.8	0.14
4.72	0.15
4.83	0.15
4.87	0.16
4.94	0.17
4.42	0.17
4.02	0.15
3.53	0.14
3.81	0.14
4.23	0.14
4.31	0.15
4.14	0.16
3.96	0.15
3.87	0.16
3.64	0.15
3.79	0.15
3.96	0.15
4.32	0.14
4.26	0.14
4.14	0.14
4.26	0.16
4.65	0.17
	4.8   4.72   4.83   4.87   4.94   4.42   4.02   3.53   3.81   4.23   4.31   4.14   3.96   3.87   3.64   3.79   3.96   4.32   4.26   4.14   4.26

## **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

