

Crater report 1079 of RG5

General information



ID: 1079

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter : $134m \pm 9.0m$

Mean depht: 3.9m ± 0.6m

d/D ratio : 0.029 ± 0.005

Circularity index: 0.9

Mean slope: 3.82

Geometric center coordinates: (3642506.395,

244794.8293)

Coordinates of the crater's lowest point : (3642522.4999999, 244792.49999999022)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	5.05	0.29
10°	4.66	0.26
20°	4.58	0.27
30°	4.53	0.24
40°	4.44	0.22
50°	4.3	0.22
60°	3.95	0.21
70°	4.0	0.22
80°	4.15	0.22
90°	4.38	0.24
100°	4.07	0.22
110°	3.94	0.22
120°	3.78	0.2






130°	3.83	0.19
140°	3.77	0.19
150°	3.58	0.2
160°	3.5	0.2
170°	3.49	0.21
180°	3.44	0.22
190°	3.09	0.21
200°	2.95	0.2
210°	3.01	0.19
220°	3.25	0.19
230°	3.22	0.19
240°	2.99	0.2
250°	2.83	0.2
260°	2.76	0.22
270°	3.11	0.24
280°	3.32	0.24
290°	3.47	0.24
300°	3.65	0.23
310°	4.08	0.22
320°	4.44	0.22
330°	4.42	0.24
340°	4.67	0.27
350°	4.84	0.28

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

