


# Crater report 1553 of RG5

#### **General information**



**ID**: 1553

Study area: RG5

**Swirl**: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 117m ± 11.0m

Mean depht: 3.4m ± 0.6m d/D ratio: 0.029 ± 0.006 Circularity index: 0.9

Mean slope : 3.4

Geometric center coordinates: (3643259.234,

240322.562)

Coordinates of the crater's lowest point : (3643282.4999999, 240297.4999999903)

#### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.28	0.25
10°	4.09	0.24
20°	3.62	0.23
30°	3.11	0.23
40°	2.64	0.22
50°	2.34	0.25
60°	2.2	0.27
70°	2.14	0.29
80°	2.17	0.28
90°	2.34	0.29
100°	2.32	0.26
110°	2.52	0.25
120°	3.04	0.24






130°	3.35	0.22
140°	3.62	0.22
150°	3.58	0.23
160°	3.51	0.23
170°	3.58	0.22
180°	3.77	0.23
190°	3.54	0.21
200°	3.48	0.2
210°	3.64	0.19
220°	3.83	0.19
230°	3.88	0.19
240°	3.72	0.19
250°	3.45	0.2
260°	3.35	0.21
270°	3.58	0.25
280°	3.51	0.25
290°	3.49	0.23
300°	3.64	0.23
310°	4.05	0.2
320°	4.29	0.2
330°	4.34	0.23
340°	4.2	0.25
350°	4.32	0.24

### **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

