


Crater report 1593 of RG5

General information



ID: 1593

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 145m ± 9.0m

Mean depht: 6.6m ± 0.6m

d/D ratio : 0.046 ± 0.005

Circularity index: 0.9

Mean slope: 6.41

Geometric center coordinates: (3636356.908,

234582.7812)

Coordinates of the crater's lowest point : (3636352.4999999, 234577.49999999042)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	5.97	0.22
10°	5.63	0.21
20°	5.41	0.22
30°	5.48	0.2
40°	6.07	0.19
50°	6.21	0.19
60°	6.36	0.2
70°	6.69	0.22
80°	6.87	0.22
90°	7.3	0.24
100°	7.11	0.22
110°	7.13	0.22
120°	7.34	0.23






130°	7.65	0.22
140°	7.51	0.22
150°	7.34	0.24
160°	6.94	0.25
170°	7.12	0.26
180°	7.2	0.25
190°	6.99	0.24
200°	6.77	0.23
210°	6.51	0.21
220°	6.74	0.2
230°	6.31	0.19
240°	6.22	0.21
250°	6.01	0.22
260°	6.2	0.23
270°	6.45	0.24
280°	6.01	0.23
290°	5.88	0.23
300°	5.77	0.21
310°	5.86	0.2
320°	5.73	0.2
330°	5.36	0.21
340°	5.17	0.22
350°	5.35	0.21

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

