


Crater report 1404 of RG2

General information



ID: 1404

Study area: RG2 **Swirl**: off-swirl

Morphology: Bowl-shaped

Estimate state of degradation : BC - C

Mean Diameter: 84m ± 4.0m Mean depht: $6.3m \pm 0.5m$ **d/D ratio** : 0.074 ± 0.007

Circularity index: 0.95

Slope: Between 4.89° et 13.15°

Mean value of TRI on the rim crest: 0.20

Geometric center coordinates: (3655572.616528014, 223171.4428980056)

Coordinates of the crater's lowest point : (3655577.0000011, 223165.0000000658)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	13.15	0.57
10°	12.75	0.53
20°	11.5	0.52
30°	11.3	0.48
40°	11.74	0.42
50°	11.6	0.42
60°	10.51	0.48
70°	9.92	0.52
80°	9.06	0.55
90°	8.72	0.57
100°	7.51	0.55
110°	5.66	0.53






120°	4.89	0.49
130°	5.29	0.44
140°	5.31	0.43
150°	6.15	0.48
160°	7.76	0.52
170°	8.36	0.54
180°	10.71	0.57
190°	11.87	0.55
200°	11.97	0.51
210°	12.51	0.47
220°	12.3	0.42
230°	12.69	0.42
240°	12.15	0.46
250°	11.79	0.51
260°	12.54	0.54
270°	11.31	0.57
280°	11.92	0.53
290°	11.72	0.5
300°	11.03	0.47
310°	11.24	0.42
320°	11.44	0.42
330°	11.35	0.48
340°	11.65	0.52
350°	11.91	0.54

Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





Topographic profiles

