


Crater report 1361 of RG5

General information



ID: 1361

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 172m ± 14.0m

Mean depht: 8.6m ± 0.6m

d/D ratio : 0.05 ± 0.005 Circularity index : 0.92

Mean slope: 6.45

Geometric center coordinates: (3640342.686,

236493.2791)

Coordinates of the crater's lowest point : (3640352.4999999, 236482.4999999037)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.19	0.2
10°	7.12	0.19
20°	7.01	0.18
30°	7.02	0.18
40°	6.99	0.17
50°	6.82	0.17
60°	6.08	0.18
70°	5.92	0.18
80°	5.85	0.2
90°	5.88	0.21
100°	5.7	0.2
110°	5.58	0.2
120°	5.61	0.19






130°	6.01	0.19
140°	6.05	0.19
150°	5.77	0.2
160°	5.68	0.2
170°	5.8	0.2
180°	6.06	0.2
190°	5.92	0.2
200°	6.13	0.19
210°	6.54	0.19
220°	7.0	0.19
230°	7.1	0.19
240°	6.81	0.19
250°	6.76	0.2
260°	6.96	0.2
270°	7.11	0.21
280°	6.61	0.2
290°	6.62	0.2
300°	6.86	0.2
310°	6.84	0.2
320°	7.2	0.19
330°	6.3	0.2
340°	6.38	0.2
350°	6.86	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

