


Crater report 1318 of RG5

General information



ID: 1318

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 111m ± 7.0m

Mean depht: 8.1m ± 0.6m

d/D ratio : 0.073 ± 0.007

Circularity index: 0.9

Mean slope: 10.04

Geometric center coordinates: (3633875.705,

235875.4956)

 $\label{lowest} \textbf{Coordinates of the crater's lowest point:}$

(3633867.4999999, 235857.4999999904)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.67	0.24
10°	7.53	0.23
20°	7.51	0.23
30°	8.13	0.23
40°	9.07	0.22
50°	10.67	0.24
60°	11.47	0.26
70°	12.1	0.27
80°	13.18	0.29
90°	13.72	0.3
100°	13.71	0.29
110°	14.32	0.3
120°	14.78	0.29






130°	14.53	0.27
140°	13.45	0.27
150°	12.82	0.25
160°	12.43	0.27
170°	12.53	0.29
180°	13.03	0.3
190°	10.91	0.27
200°	10.43	0.26
210°	10.14	0.23
220°	9.42	0.22
230°	8.6	0.2
240°	7.47	0.21
250°	7.87	0.21
260°	8.18	0.22
270°	8.19	0.22
280°	7.59	0.21
290°	7.45	0.21
300°	7.31	0.2
310°	7.25	0.19
320°	7.02	0.2
330°	6.87	0.21
340°	6.96	0.21
350°	7.12	0.22

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

