


Crater report 1381 of RG5

General information



ID: 1381

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 259m ± 8.0m

Mean depht: $11.7m \pm 0.6m$

d/D ratio : 0.045 ± 0.003

Circularity index: 0.92

Mean slope: 6.62

Geometric center coordinates: (3641971.663,

239337.488)

 $\label{lowest} \textbf{Coordinates of the crater's lowest point:}$

(3641972.4999999, 239302.4999999903)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.77	0.18
10°	6.61	0.18
20°	6.3	0.17
30°	6.8	0.18
40°	7.54	0.18
50°	7.72	0.18
60°	8.1	0.2
70°	8.45	0.2
80°	8.83	0.21
90°	9.41	0.22
100°	8.79	0.21
110°	8.57	0.2
120°	8.53	0.19






130°	8.51	0.18
140°	7.98	0.17
150°	7.74	0.18
160°	7.5	0.18
170°	7.74	0.19
180°	7.8	0.19
190°	7.24	0.18
200°	6.22	0.16
210°	5.88	0.15
220°	5.03	0.13
230°	4.74	0.12
240°	4.29	0.13
250°	4.28	0.13
260°	4.26	0.13
270°	4.41	0.14
280°	4.37	0.14
290°	4.43	0.14
300°	4.8	0.14
310°	5.11	0.14
320°	5.56	0.14
330°	5.7	0.15
340°	5.98	0.16
350°	6.27	0.17

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

