


Crater report 1280 of RG5

General information



ID: 1280

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped **Mean Diameter**: 96m ± 6.0m

 $\textbf{Mean depht:} 3.9 \text{m} \pm 0.6 \text{m}$

d/D ratio : 0.04 ± 0.007 Circularity index : 0.92

Mean slope: 5.11

Geometric center coordinates: (3633853.835,

237090.1407)

Coordinates of the crater's lowest point : (3633862.4999999, 237082.4999999037)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.02	0.32
10°	5.61	0.3
20°	5.35	0.28
30°	5.3	0.27
40°	5.32	0.25
50°	5.14	0.25
60°	4.9	0.24
70°	4.68	0.27
80°	4.97	0.26
90°	5.17	0.27
100°	5.27	0.26
110°	5.16	0.25
120°	4.59	0.24






130°	5.16	0.22
140°	5.15	0.22
150°	4.74	0.23
160°	4.69	0.25
170°	4.59	0.26
180°	4.59	0.25
190°	4.28	0.26
200°	4.11	0.25
210°	3.73	0.24
220°	4.14	0.22
230°	4.44	0.22
240°	4.25	0.24
250°	4.76	0.25
260°	5.05	0.26
270°	5.48	0.27
280°	5.43	0.26
290°	5.54	0.27
300°	5.7	0.27
310°	6.16	0.25
320°	6.3	0.28
330°	6.3	0.27
340°	5.92	0.28
350°	5.86	0.3

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

