


Crater report 1024 of RG5

General information



ID: 1024

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 162m ± 10.0m

Mean depht: $7.9m \pm 0.6m$ **d/D ratio**: 0.049 ± 0.005

Circularity index: 0.91

Mean slope: 6.64

Geometric center coordinates: (3641236.53,

241850.3)

Coordinates of the crater's lowest point : (3641237.4999999, 241847.4999999028)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.77	0.21
10°	6.39	0.2
20°	6.14	0.19
30°	6.16	0.18
40°	6.74	0.18
50°	6.79	0.18
60°	6.49	0.19
70°	6.25	0.19
80°	6.29	0.2
90°	6.48	0.21
100°	6.01	0.21
110°	5.32	0.21
120°	5.27	0.2






130°	5.31	0.19
140°	5.45	0.19
150°	5.5	0.2
160°	6.04	0.23
170°	6.94	0.24
180°	7.08	0.24
190°	6.9	0.23
200°	6.84	0.22
210°	7.12	0.21
220°	7.08	0.19
230°	7.12	0.19
240°	6.94	0.2
250°	7.15	0.22
260°	7.64	0.23
270°	7.87	0.24
280°	7.58	0.23
290°	7.21	0.22
300°	7.35	0.21
310°	7.46	0.2
320°	7.32	0.19
330°	6.88	0.2
340°	6.67	0.2
350°	6.57	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

