


Crater report 3359 of RG5

General information



ID: 3359

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter : $103m \pm 9.0m$

Mean depht : $3.7m \pm 0.6m$

d/D ratio : 0.036 ± 0.006

Circularity index: 0.91

Mean slope: 4.55

Geometric center coordinates: (3642168.371,

211390.7787)

Coordinates of the crater's lowest point : (3642182.4999999, 211372.49999999086)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	5.14	0.29
10°	4.69	0.26
20°	4.47	0.25
30°	4.41	0.24
40°	4.46	0.25
50°	4.53	0.25
60°	4.5	0.25
70°	4.62	0.27
80°	4.78	0.28
90°	5.19	0.29
100°	5.03	0.28
110°	4.99	0.27
120°	5.04	0.25






130°	5.05	0.22
140°	4.83	0.22
150°	4.58	0.24
160°	4.32	0.25
170°	4.45	0.26
180°	4.54	0.27
190°	4.39	0.24
200°	4.18	0.25
210°	4.14	0.23
220°	4.34	0.2
230°	4.43	0.2
240°	4.28	0.23
250°	4.22	0.24
260°	4.23	0.26
270°	4.37	0.27
280°	4.09	0.26
290°	3.88	0.24
300°	4.02	0.25
310°	4.47	0.25
320°	4.83	0.25
330°	4.72	0.24
340°	4.82	0.27
350°	4.8	0.26

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

