


Crater report 3349 of RG5

General information



ID: 3349

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 125m ± 6.0m

Mean depht: $6.0m \pm 0.7m$

d/D ratio : 0.048 ± 0.006

Circularity index: 0.93

Mean slope: 6.1

Geometric center coordinates: (3641846.393,

211845.0476)

Coordinates of the crater's lowest point :

(3641862.4999999, 211822.49999999086)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.95	0.27
10°	6.09	0.26
20°	5.55	0.27
30°	5.32	0.27
40°	5.08	0.25
50°	4.67	0.25
60°	4.59	0.27
70°	4.63	0.29
80°	4.84	0.28
90°	5.24	0.29
100°	5.11	0.28
110°	5.14	0.27
120°	5.32	0.25






130°	6.13	0.2
140°	6.32	0.2
150°	6.18	0.21
160°	6.15	0.22
170°	6.34	0.23
180°	6.52	0.24
190°	6.06	0.21
200°	5.76	0.2
210°	6.0	0.2
220°	6.34	0.19
230°	6.36	0.19
240°	6.07	0.19
250°	6.03	0.2
260°	6.53	0.2
270°	7.06	0.21
280°	7.13	0.21
290°	6.93	0.22
300°	7.02	0.21
310°	7.33	0.2
320°	7.46	0.2
330°	7.13	0.23
340°	7.15	0.24
350°	6.96	0.26

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

