


Crater report 2862 of RG5

General information



ID: 2862

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 223m ± 13.0m

Mean depht: 8.1m ± 0.8m **d/D ratio**: 0.036 ± 0.004

Circularity index: 0.92

Mean slope: 4.6

Geometric center coordinates: (3639302.276,

216775.7196)

Coordinates of the crater's lowest point : (3639307.4999999, 216752.49999999077)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.02	0.21
10°	3.75	0.21
20°	3.64	0.18
30°	3.63	0.18
40°	3.78	0.17
50°	4.13	0.17
60°	4.04	0.18
70°	4.19	0.19
80°	4.19	0.19
90°	4.6	0.21
100°	4.51	0.21
110°	4.72	0.2
120°	4.84	0.2






130°	5.07	0.18
140°	5.06	0.18
150°	4.73	0.17
160°	4.93	0.18
170°	5.29	0.17
180°	5.85	0.18
190°	5.69	0.16
200°	5.55	0.16
210°	5.24	0.15
220°	5.14	0.14
230°	4.98	0.14
240°	4.31	0.14
250°	4.1	0.14
260°	4.3	0.15
270°	4.7	0.16
280°	4.79	0.16
290°	4.87	0.16
300°	4.84	0.15
310°	4.88	0.14
320°	4.7	0.15
330°	4.29	0.16
340°	4.09	0.18
350°	4.0	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

