


Crater report 3077 of RG5

General information



ID:3077

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 198m ± 12.0m

Mean depht: $13.0m \pm 0.6m$

d/D ratio: 0.066 ± 0.005

Circularity index: 0.91

Mean slope: 8.7

Geometric center coordinates: (3643848.427,

218430.0259)

Coordinates of the crater's lowest point : (3643867.4999999, 218412.49999999074)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	8.87	0.21
10°	8.57	0.2
20°	8.56	0.19
30°	8.62	0.19
40°	9.71	0.17
50°	9.9	0.17
60°	9.57	0.18
70°	9.59	0.19
80°	9.79	0.2
90°	9.77	0.21
100°	8.84	0.2
110°	8.59	0.19
120°	7.96	0.19






130°	8.17	0.17
140°	8.07	0.17
150°	8.03	0.17
160°	8.4	0.18
170°	8.82	0.18
180°	8.79	0.19
190°	8.18	0.18
200°	8.22	0.18
210°	8.43	0.17
220°	8.88	0.16
230°	8.67	0.16
240°	8.23	0.16
250°	8.33	0.17
260°	8.63	0.18
270°	9.06	0.18
280°	8.62	0.18
290°	8.38	0.17
300°	8.52	0.18
310°	9.02	0.17
320°	9.2	0.17
330°	8.36	0.18
340°	7.96	0.19
350°	8.05	0.19

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

