


# Crater report 888 of RG2

#### **General information**



**ID**:888

Study area: RG2 Swirl: on-swirl

Morphology: Bowl-shaped

Estimate state of degradation : BC - C

**Mean Diameter**: 59m ± 8.0m **Mean depht**: 3.1m ± 0.3m **d/D ratio**: 0.053 ± 0.008

Circularity index: 0.91

Slope: Between 7.05° et 10.67°

Mean value of TRI on the rim crest: 0.34

**Geometric center coordinates :** (3655611.6080763075, 228962.4652793937)

**Coordinates of the crater's lowest point**: (3655601.0000011, 228953.00000006755)

#### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.95	0.57
10°	7.41	0.55
20°	7.33	0.5
30°	7.26	0.48
40°	7.52	0.42
50°	7.88	0.42
60°	7.21	0.49
70°	8.11	0.51
80°	10.08	0.55
90°	10.28	0.57
100°	8.48	0.55
110°	7.63	0.5






120°	7.14	0.49
130°	7.64	0.43
140°	7.84	0.43
150°	7.31	0.48
160°	7.85	0.52
170°	7.94	0.55
180°	8.24	0.57
190°	8.23	0.54
200°	8.05	0.53
210°	9.62	0.49
220°	10.29	0.46
230°	10.38	0.46
240°	10.67	0.49
250°	10.26	0.52
260°	9.44	0.52
270°	9.9	0.57
280°	8.5	0.52
290°	8.14	0.52
300°	8.69	0.49
310°	8.46	0.46
320°	7.62	0.45
330°	7.22	0.49
340°	7.05	0.5
350°	7.62	0.55

### Topographic roughness index (TRI)

The Topographic Roughness Index (TRI) is a measure used to quantify the ruggedeness or the unevenness of terrain. It reflects how much elevation change over a given area.





## **Topographic profiles**

