


Crater report 4022 of RG5

General information



ID: 4022

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 150m ± 9.0m

Mean depht: $7.3m \pm 0.6m$

d/D ratio : 0.048 ± 0.005

Circularity index: 0.94

Mean slope: 6.67

Geometric center coordinates: (3634862.342,

204265.6842)

Coordinates of the crater's lowest point : (3634877.4999999, 204267.49999999104)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	8.64	0.27
10°	7.95	0.26
20°	7.12	0.25
30°	5.89	0.23
40°	5.27	0.2
50°	4.9	0.2
60°	4.56	0.22
70°	4.8	0.21
80°	5.44	0.21
90°	5.99	0.22
100°	5.98	0.21
110°	6.31	0.19
120°	5.52	0.19






5.59	0.18
5.55	0.18
5.38	0.19
5.62	0.19
5.57	0.2
5.68	0.21
5.24	0.2
5.26	0.18
5.3	0.18
6.21	0.18
6.64	0.18
7.0	0.2
7.1	0.21
7.73	0.22
8.67	0.25
8.37	0.24
8.14	0.22
8.6	0.22
9.02	0.22
8.92	0.22
8.99	0.23
8.52	0.25
8.76	0.26
	5.55 5.38 5.62 5.57 5.68 5.24 5.26 5.3 6.21 6.64 7.0 7.1 7.73 8.67 8.37 8.14 8.6 9.02 8.92 8.99 8.52

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

