


Crater report 815 of RG5

General information



ID:815

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 131m ± 8.0m

Mean depht: 3.1m ± 0.6m

d/D ratio : 0.023 ± 0.005

Circularity index: 0.9

Mean slope: 3.16

Geometric center coordinates: (3644986.125,

247464.2401)

Coordinates of the crater's lowest point : (3644997.4999998994, 247452.49999999016)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	3.21	0.27
10°	3.08	0.26
20°	3.15	0.27
30°	3.56	0.24
40°	3.83	0.22
50°	4.2	0.25
60°	4.3	0.24
70°	4.2	0.27
80°	4.01	0.26
90°	4.15	0.29
100°	3.78	0.28
110°	3.48	0.27
120°	3.24	0.24






130°	3.28	0.22
140°	3.09	0.22
150°	2.76	0.22
160°	2.62	0.23
170°	2.52	0.22
180°	2.61	0.23
190°	2.58	0.22
200°	2.61	0.2
210°	2.77	0.2
220°	3.16	0.19
230°	3.26	0.19
240°	3.02	0.2
250°	3.0	0.21
260°	3.07	0.23
270°	3.1	0.23
280°	2.74	0.22
290°	2.5	0.2
300°	2.47	0.2
310°	2.65	0.19
320°	2.8	0.21
330°	2.88	0.21
340°	2.94	0.23
350°	3.07	0.26

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

