


Crater report 99 of RG5

General information



ID:99

Study area: RG5 Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 124m ± 9.0m

Mean depht : $7.4m \pm 0.6m$

d/D ratio : 0.059 ± 0.006 Circularity index : 0.91

Mean slope: 9.22

Geometric center coordinates: (3635848.277,

251760.9651)

Coordinates of the crater's lowest point : (3635872.4999999, 251757.49999999008)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	13.5	0.3
10°	12.9	0.29
20°	14.22	0.29
30°	14.31	0.29
40°	14.58	0.26
50°	13.1	0.27
60°	11.28	0.26
70°	9.05	0.26
80°	7.69	0.24
90°	7.94	0.25
100°	6.88	0.24
110°	5.88	0.22
120°	5.03	0.2






130°	4.99	0.18
140°	4.84	0.18
150°	4.54	0.18
160°	4.34	0.19
170°	4.43	0.2
180°	4.81	0.21
190°	4.84	0.2
200°	4.84	0.19
210°	5.05	0.19
220°	5.64	0.19
230°	6.88	0.2
240°	7.9	0.22
250°	8.41	0.24
260°	9.31	0.26
270°	10.31	0.26
280°	10.6	0.27
290°	11.72	0.28
300°	12.21	0.26
310°	13.22	0.27
320°	14.13	0.27
330°	14.08	0.29
340°	13.81	0.3
350°	14.63	0.31

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

