


Crater report 2859 of RG5

General information



ID: 2859

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 179m ± 11.0m

Mean depht: 8.7m ± 0.6m d/D ratio: 0.048 ± 0.005 Circularity index: 0.93

Mean slope : 6.6

Geometric center coordinates: (3641622.917,

218816.0043)

Coordinates of the crater's lowest point : (3641632.4999999, 218797.49999999074)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.74	0.22
10°	7.51	0.21
20°	7.31	0.21
30°	7.23	0.2
40°	7.3	0.19
50°	7.12	0.19
60°	6.53	0.2
70°	6.41	0.22
80°	6.34	0.22
90°	6.52	0.24
100°	5.72	0.22
110°	5.52	0.2
120°	5.53	0.2






130°	5.65	0.19
140°	6.04	0.18
150°	6.18	0.19
160°	6.59	0.19
170°	7.1	0.2
180°	7.68	0.21
190°	7.18	0.19
200°	6.74	0.19
210°	6.33	0.17
220°	6.1	0.16
230°	6.3	0.17
240°	6.4	0.18
250°	6.29	0.18
260°	6.35	0.19
270°	6.6	0.2
280°	6.08	0.18
290°	6.05	0.18
300°	6.21	0.18
310°	6.84	0.18
320°	7.04	0.18
330°	6.85	0.19
340°	6.89	0.2
350°	7.35	0.21

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

