


# Crater report 1898 of RG5

#### **General information**



**ID**: 1898

Study area: RG5

**Swirl**: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 219m ± 13.0m

**Mean depht**: 8.1m ± 0.6m **d/D ratio**: 0.037 ± 0.004

Circularity index: 0.9

Mean slope: 4.83

Geometric center coordinates: (3635689.23,

228938.4402)

**Coordinates of the crater's lowest point :** (3635687.4999999, 228932.499999905)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.38	0.19
10°	4.22	0.17
20°	4.21	0.16
30°	4.0	0.15
40°	4.14	0.15
50°	4.44	0.16
60°	4.35	0.16
70°	4.48	0.17
80°	4.71	0.17
90°	5.08	0.18
100°	4.9	0.17
110°	4.81	0.17
120°	4.81	0.16






130°	5.12	0.16
140°	5.29	0.16
150°	5.39	0.17
160°	5.61	0.18
170°	5.8	0.19
180°	5.89	0.2
190°	5.48	0.19
200°	5.18	0.18
210°	5.08	0.17
220°	5.06	0.17
230°	5.21	0.16
240°	5.57	0.18
250°	5.65	0.19
260°	5.74	0.2
270°	5.72	0.21
280°	5.15	0.19
290°	4.62	0.18
300°	4.08	0.16
310°	4.06	0.15
320°	4.0	0.16
330°	3.78	0.17
340°	3.77	0.18
350°	4.14	0.19

## **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

