


Crater report 1192 of RG5

General information



ID: 1192

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 198m ± 10.0m

Mean depht : $8.4m \pm 0.8m$ d/D ratio : 0.042 ± 0.004

Circularity index: 0.9

Mean slope: 5.71

Geometric center coordinates: (3643856.69,

243721.1736)

Coordinates of the crater's lowest point : (3643877.4999999, 243707.4999999022)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	7.21	0.22
10°	6.58	0.21
20°	6.19	0.2
30°	6.26	0.2
40°	6.53	0.19
50°	6.58	0.19
60°	6.24	0.2
70°	6.08	0.2
80°	5.73	0.2
90°	5.44	0.21
100°	4.64	0.21
110°	4.0	0.19
120°	3.42	0.19






130°	3.0	0.18
140°	2.83	0.18
150°	3.04	0.16
160°	3.71	0.16
170°	4.69	0.17
180°	6.05	0.18
190°	6.13	0.18
200°	5.4	0.16
210°	5.26	0.15
220°	6.45	0.15
230°	6.85	0.16
240°	6.48	0.17
250°	6.44	0.17
260°	6.43	0.18
270°	6.36	0.19
280°	5.97	0.19
290°	5.87	0.19
300°	6.14	0.18
310°	6.34	0.18
320°	6.45	0.18
330°	6.71	0.2
340°	6.78	0.2
350°	7.16	0.22

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

