

Crater report 862 of RG5

General information



ID:862

Study area: RG5 Swirl: off-swirl

Morphology: Bowl-shaped

...e.p...e.gy 12em enapea

Mean Diameter : 187m ± 10.0m

Mean depht: 7.6m ± 0.6m **d/D ratio**: 0.041 ± 0.004

Circularity index: 0.9

Mean slope: 5.66

Geometric center coordinates: (3636193.617,

243828.983)

Coordinates of the crater's lowest point : (3636207.4999999, 243827.4999999022)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.16	0.21
10°	5.91	0.2
20°	5.75	0.19
30°	5.9	0.19
40°	5.86	0.18
50°	5.59	0.18
60°	5.11	0.18
70°	5.06	0.19
80°	5.21	0.2
90°	5.36	0.2
100°	4.95	0.2
110°	4.48	0.18
120°	4.27	0.18






130°	4.23	0.18
140°	4.27	0.17
150°	4.41	0.18
160°	4.7	0.18
170°	5.48	0.19
180°	5.98	0.2
190°	6.0	0.2
200°	5.79	0.19
210°	5.78	0.19
220°	6.52	0.19
230°	6.82	0.2
240°	6.89	0.2
250°	6.34	0.19
260°	6.12	0.2
270°	6.57	0.21
280°	6.25	0.2
290°	5.9	0.19
300°	6.05	0.2
310°	6.37	0.19
320°	6.31	0.19
330°	5.74	0.19
340°	5.63	0.19
350°	5.84	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

