


Crater report 1586 of RG5

General information



ID: 1586

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 157m ± 8.0m

Mean depht: $6.5m \pm 0.6m$

d/D ratio : 0.041 ± 0.004

Circularity index: 0.94

Mean slope: 5.48

Geometric center coordinates: (3634843.758,

231783.7543)

Coordinates of the crater's lowest point : (3634857.4999999, 231767.49999999045)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	5.97	0.22
10°	5.27	0.21
20°	4.84	0.21
30°	4.84	0.22
40°	4.74	0.2
50°	4.59	0.2
60°	4.38	0.21
70°	4.51	0.22
80°	4.7	0.22
90°	5.27	0.24
100°	5.31	0.22
110°	5.38	0.22
120°	5.59	0.2






130°	6.01	0.19
140°	6.03	0.19
150°	5.73	0.2
160°	5.8	0.22
170°	6.0	0.22
180°	6.22	0.22
190°	5.92	0.21
200°	5.66	0.21
210°	5.3	0.2
220°	5.2	0.19
230°	5.24	0.19
240°	4.91	0.19
250°	4.94	0.19
260°	5.28	0.2
270°	5.72	0.21
280°	5.58	0.2
290°	5.51	0.19
300°	5.71	0.19
310°	6.34	0.19
320°	6.46	0.19
330°	6.23	0.2
340°	5.97	0.2
350°	6.05	0.21

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

