


Crater report 782 of RG5

General information



ID: 782

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 187m ± 14.0m

Mean depht: $10.2m \pm 0.6m$

d/D ratio : 0.054 ± 0.005

Circularity index: 0.9

Mean slope: 7.6

Geometric center coordinates: (3643175.056,

247662.0802)

Coordinates of the crater's lowest point : (3643187.4999999, 247647.49999999016)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	8.46	0.21
10°	8.31	0.21
20°	8.39	0.2
30°	8.79	0.2
40°	9.62	0.2
50°	9.33	0.19
60°	8.75	0.2
70°	8.86	0.2
80°	9.14	0.21
90°	9.65	0.22
100°	8.76	0.21
110°	8.05	0.2
120°	7.41	0.19






130°	7.59	0.18
140°	7.58	0.18
150°	7.71	0.19
160°	8.02	0.2
170°	7.9	0.2
180°	8.23	0.21
190°	7.75	0.2
200°	7.48	0.19
210°	7.35	0.19
220°	7.45	0.17
230°	7.34	0.18
240°	6.51	0.18
250°	6.17	0.18
260°	6.29	0.19
270°	6.74	0.2
280°	6.35	0.2
290°	5.76	0.17
300°	5.6	0.17
310°	5.86	0.16
320°	6.08	0.16
330°	6.16	0.17
340°	6.73	0.19
350°	7.54	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

