


Crater report 3159 of RG5

General information



ID: 3159

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 222m ± 14.0m

Mean depht: $10.3m \pm 0.8m$

d/D ratio : 0.046 ± 0.005

Circularity index: 0.91

Mean slope: 6.06

Geometric center coordinates: (3637629.306,

212874.9237)

Coordinates of the crater's lowest point : (3637627.4999999, 212872.49999999086)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	5.85	0.18
10°	5.33	0.16
20°	5.05	0.16
30°	5.03	0.16
40°	5.14	0.15
50°	5.28	0.15
60°	5.2	0.16
70°	5.14	0.17
80°	5.3	0.17
90°	5.51	0.18
100°	5.45	0.18
110°	5.3	0.18
120°	5.48	0.18






130°	5.65	0.17
140°	5.48	0.17
150°	5.47	0.19
160°	5.48	0.2
170°	5.59	0.2
180°	5.92	0.21
190°	5.76	0.2
200°	5.6	0.19
210°	5.61	0.18
220°	6.02	0.17
230°	6.68	0.16
240°	6.74	0.16
250°	7.17	0.17
260°	7.48	0.17
270°	8.15	0.18
280°	7.82	0.17
290°	7.69	0.17
300°	7.5	0.16
310°	7.51	0.15
320°	7.11	0.15
330°	6.56	0.15
340°	6.21	0.16
350°	5.92	0.17

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

