


Crater report 1391 of RG5

General information



ID: 1391

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 135m ± 7.0m

Mean depht: 7.1m ± 0.6m

d/D ratio : 0.053 ± 0.005

Circularity index: 0.92

Mean slope: 7.35

Geometric center coordinates: (3638899.935,

239521.2903)

Coordinates of the crater's lowest point : (3638902.4999999, 239507.499999903)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	8.4	0.25
10°	8.17	0.24
20°	7.82	0.22
30°	7.97	0.23
40°	8.26	0.22
50°	8.3	0.22
60°	8.07	0.23
70°	8.11	0.24
80°	8.16	0.23
90°	8.72	0.25
100°	8.59	0.26
110°	8.08	0.24
120°	7.97	0.22






130°	7.98	0.22
140°	7.66	0.22
150°	7.16	0.23
160°	6.82	0.23
170°	6.89	0.23
180°	7.15	0.24
190°	6.78	0.23
200°	6.49	0.23
210°	6.69	0.23
220°	6.76	0.2
230°	6.66	0.2
240°	6.26	0.23
250°	6.28	0.23
260°	6.38	0.23
270°	6.64	0.24
280°	6.5	0.23
290°	6.41	0.23
300°	6.67	0.21
310°	7.16	0.2
320°	7.26	0.2
330°	6.91	0.22
340°	7.18	0.23
350°	7.4	0.22

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

