


# Crater report 2413 of RG5

#### **General information**



**ID**: 2413

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 277m ± 18.0m

Mean depht:  $14.8m \pm 0.7m$ 

**d/D ratio** :  $0.053 \pm 0.004$ 

Circularity index: 0.9

Mean slope: 6.69

Geometric center coordinates: (3640355.516,

222967.099)

Coordinates of the crater's lowest point : (3640352.4999999, 222952.4999999063)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.81	0.15
10°	6.19	0.15
20°	5.68	0.14
30°	5.39	0.14
40°	5.45	0.13
50°	5.48	0.13
60°	5.42	0.14
70°	5.19	0.16
80°	5.7	0.16
90°	6.28	0.17
100°	6.26	0.16
110°	6.35	0.16
120°	6.73	0.15






130°	7.37	0.15
140°	7.76	0.15
150°	7.74	0.16
160°	7.68	0.17
170°	7.73	0.17
180°	7.77	0.17
190°	7.13	0.16
200°	6.71	0.16
210°	6.64	0.15
220°	6.86	0.14
230°	6.69	0.14
240°	6.35	0.14
250°	6.55	0.14
260°	6.99	0.15
270°	7.5	0.15
280°	7.41	0.15
290°	7.44	0.15
300°	7.37	0.15
310°	7.64	0.14
320°	7.19	0.14
330°	6.51	0.14
340°	6.37	0.15
350°	6.61	0.15

## **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

