

Crater report 687 of RG5

General information



ID:687

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter : $162m \pm 9.0m$

Mean depht : $4.7m \pm 0.6m$

d/D ratio : 0.029 ± 0.004

Circularity index: 0.92

Mean slope: 4.0

Geometric center coordinates: (3641207.795,

246781.6753)

Coordinates of the crater's lowest point : (3641222.4999999, 246767.49999999016)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.08	0.25
10°	3.8	0.22
20°	3.63	0.22
30°	3.34	0.21
40°	3.52	0.21
50°	3.77	0.2
60°	3.98	0.21
70°	4.49	0.22
80°	4.7	0.21
90°	5.14	0.23
100°	5.02	0.22
110°	4.82	0.22
120°	4.92	0.21






130°	5.0	0.2
140°	4.75	0.2
150°	4.32	0.21
160°	4.12	0.22
170°	4.01	0.21
180°	3.87	0.21
190°	3.57	0.2
200°	3.58	0.2
210°	3.93	0.19
220°	4.06	0.18
230°	3.84	0.17
240°	3.61	0.18
250°	3.88	0.19
260°	4.06	0.21
270°	4.01	0.22
280°	3.51	0.21
290°	3.26	0.2
300°	3.21	0.19
310°	3.53	0.21
320°	3.62	0.21
330°	3.55	0.21
340°	3.6	0.23
350°	3.76	0.24

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

