


Crater report 1088 of RG5

General information



ID: 1088

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 109m ± 9.0m

Mean depht : $3.4m \pm 0.6m$

d/D ratio : 0.031 ± 0.006

Circularity index: 0.91

Mean slope: 3.98

Geometric center coordinates: (3639351.139,

241949.1423)

Coordinates of the crater's lowest point :

(3639357.4999999, 241937.49999999028)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	3.59	0.25
10°	3.61	0.24
20°	3.78	0.23
30°	3.69	0.23
40°	3.87	0.22
50°	4.17	0.22
60°	4.01	0.23
70°	4.18	0.25
80°	4.24	0.26
90°	4.7	0.29
100°	4.3	0.28
110°	4.12	0.27
120°	4.08	0.24






130°	4.33	0.25
140°	4.35	0.25
150°	4.34	0.27
160°	4.21	0.27
170°	4.35	0.28
180°	4.69	0.29
190°	4.61	0.28
200°	4.61	0.27
210°	4.71	0.27
220°	4.69	0.25
230°	4.45	0.25
240°	3.99	0.25
250°	3.79	0.24
260°	3.61	0.24
270°	3.53	0.24
280°	3.24	0.23
290°	3.24	0.22
300°	3.26	0.2
310°	3.44	0.19
320°	3.37	0.19
330°	3.23	0.21
340°	3.35	0.23
350°	3.42	0.25

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

