


# Crater report 3709 of RG5

#### **General information**



**ID**: 3709

Study area: RG5

**Swirl**: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 161m ± 9.0m

Mean depht: 6.6m ± 0.6m

d/D ratio : 0.041 ± 0.004

Circularity index: 0.92

Mean slope: 5.53

Geometric center coordinates: (3638919.694,

210358.6263)

Coordinates of the crater's lowest point :

(3638922.4999999, 210352.4999999999)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	5.86	0.23
10°	5.68	0.21
20°	5.51	0.2
30°	5.66	0.2
40°	5.9	0.19
50°	5.67	0.2
60°	5.35	0.21
70°	5.06	0.22
80°	5.07	0.22
90°	5.18	0.22
100°	5.03	0.22
110°	4.94	0.22
120°	4.89	0.21






130°	5.07	0.19
140°	5.24	0.19
150°	4.9	0.18
160°	5.11	0.19
170°	5.19	0.2
180°	5.44	0.21
190°	5.25	0.2
200°	5.02	0.19
210°	5.2	0.19
220°	5.9	0.19
230°	6.2	0.19
240°	6.09	0.2
250°	6.26	0.22
260°	6.3	0.21
270°	6.71	0.22
280°	6.26	0.21
290°	6.04	0.22
300°	5.74	0.21
310°	5.77	0.19
320°	5.62	0.19
330°	5.31	0.2
340°	5.22	0.21
350°	5.44	0.21

## **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

