


Crater report 1057 of RG5

General information



ID: 1057

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 192m ± 10.0m

Mean depht: 6.0m ± 0.6m **d/D ratio**: 0.031 ± 0.004

Circularity index: 0.91

Mean slope: 3.92

Geometric center coordinates: (3641415.916,

242972.2932)

Coordinates of the crater's lowest point : (3641427.4999999, 242967.4999999025)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	4.67	0.21
10°	4.45	0.2
20°	4.3	0.19
30°	4.26	0.19
40°	4.29	0.18
50°	4.12	0.18
60°	3.81	0.18
70°	3.75	0.18
80°	3.54	0.19
90°	3.8	0.19
100°	3.59	0.18
110°	3.55	0.18
120°	3.56	0.17






130°	3.68	0.16
140°	3.7	0.17
150°	3.6	0.17
160°	3.74	0.17
170°	4.12	0.18
180°	4.43	0.18
190°	4.51	0.18
200°	4.62	0.18
210°	4.5	0.17
220°	4.4	0.17
230°	4.09	0.17
240°	3.71	0.17
250°	3.54	0.17
260°	3.47	0.18
270°	3.57	0.18
280°	3.51	0.18
290°	3.46	0.19
300°	3.41	0.19
310°	3.45	0.19
320°	3.62	0.19
330°	3.89	0.2
340°	4.13	0.2
350°	4.43	0.21

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

