


Crater report 2936 of RG5

General information



ID: 2936

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: $173m \pm 9.0m$

Mean depht: $5.5m \pm 0.6m$

d/D ratio : 0.032 ± 0.004

Circularity index: 0.91

Mean slope: 4.0

Geometric center coordinates: (3638769.666,

215900.1431)

Coordinates of the crater's lowest point :

(3638772.4999999, 215892.4999999908)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	3.54	0.21
10°	3.38	0.2
20°	3.18	0.19
30°	3.23	0.19
40°	3.33	0.18
50°	3.31	0.18
60°	3.37	0.19
70°	3.38	0.2
80°	3.5	0.21
90°	3.86	0.21
100°	3.73	0.21
110°	3.8	0.19
120°	3.86	0.19






130°	4.27	0.18
140°	4.49	0.18
150°	4.5	0.19
160°	4.4	0.19
170°	4.71	0.2
180°	4.89	0.23
190°	4.35	0.21
200°	4.02	0.2
210°	3.96	0.2
220°	4.34	0.19
230°	4.49	0.19
240°	4.27	0.19
250°	4.47	0.19
260°	4.71	0.2
270°	4.94	0.21
280°	4.56	0.19
290°	4.22	0.18
300°	4.34	0.18
310°	4.32	0.17
320°	3.9	0.17
330°	3.6	0.17
340°	3.39	0.19
350°	3.36	0.19

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

