


Crater report 1569 of RG5

General information



ID: 1569

Study area: RG5 Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 170m ± 8.0m

Mean depht: $12.6m \pm 0.6m$

d/D ratio : 0.074 ± 0.005

Circularity index: 0.92

Mean slope: 10.6

Geometric center coordinates: (3636631.838,

232007.2525)

Coordinates of the crater's lowest point : (3636642.4999999, 231992.49999999045)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	14.13	0.24
10°	13.51	0.22
20°	12.51	0.22
30°	12.47	0.2
40°	12.53	0.2
50°	12.46	0.2
60°	12.4	0.22
70°	11.64	0.22
80°	11.45	0.22
90°	12.17	0.23
100°	11.24	0.22
110°	10.51	0.21
120°	10.52	0.2






10.84	0.2
10.22	0.2
9.26	0.2
9.8	0.21
9.96	0.22
10.05	0.22
9.47	0.21
9.28	0.2
8.75	0.18
8.92	0.17
9.06	0.17
8.49	0.18
8.69	0.18
8.91	0.18
9.62	0.19
8.91	0.18
9.04	0.18
8.93	0.18
10.54	0.17
11.07	0.17
10.84	0.18
11.47	0.19
11.99	0.21
	10.22 9.26 9.8 9.96 10.05 9.47 9.28 8.75 8.92 9.06 8.49 8.69 8.91 9.62 8.91 9.04 8.93 10.54 11.07 10.84 11.47

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

