


# Crater report 996 of RG5

#### **General information**



**ID**: 996

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 224m ± 16.0m

Mean depht:  $21.7m \pm 0.8m$ 

**d/D ratio**: 0.097 ± 0.008

**Circularity index:** 0.91

Mean slope: 13.06

Geometric center coordinates: (3641207.25,

241525.3365)

**Coordinates of the crater's lowest point :** (3641217.4999999, 241512.4999999028)

### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	14.87	0.19
10°	14.32	0.18
20°	13.59	0.17
30°	13.82	0.16
40°	14.49	0.16
50°	14.21	0.16
60°	13.6	0.17
70°	13.37	0.17
80°	13.46	0.18
90°	14.55	0.19
100°	14.05	0.18
110°	12.79	0.16
120°	12.0	0.16






130°	11.6	0.15
140°	10.85	0.15
150°	10.8	0.16
160°	10.44	0.17
170°	10.54	0.17
180°	10.54	0.17
190°	9.93	0.17
200°	9.71	0.17
210°	10.38	0.17
220°	11.79	0.16
230°	12.27	0.16
240°	12.75	0.17
250°	14.28	0.18
260°	14.97	0.18
270°	15.06	0.19
280°	14.48	0.18
290°	13.71	0.16
300°	13.76	0.16
310°	14.22	0.15
320°	14.97	0.16
330°	15.12	0.16
340°	14.41	0.17
350°	14.37	0.18

## **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

