


Crater report 1259 of RG5

General information



ID: 1259

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter: 143m ± 11.0m

Mean depht: 6.4m ± 1.1m **d/D ratio**: 0.044 ± 0.008

Circularity index: 0.9

Mean slope: 4.9

Geometric center coordinates: (3635145.435,

240742.5022)

Coordinates of the crater's lowest point : (3635157.4999999, 240737.4999999028)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	3.43	0.25
10°	3.1	0.26
20°	3.06	0.27
30°	3.32	0.27
40°	3.48	0.28
50°	3.08	0.28
60°	2.75	0.27
70°	2.56	0.27
80°	2.7	0.28
90°	3.07	0.29
100°	3.19	0.26
110°	3.34	0.23
120°	3.71	0.23






130°	4.4	0.2
140°	4.92	0.19
150°	5.58	0.2
160°	6.08	0.19
170°	6.72	0.2
180°	7.46	0.2
190°	7.21	0.19
200°	7.04	0.18
210°	7.11	0.17
220°	7.6	0.16
230°	7.66	0.16
240°	7.23	0.16
250°	6.72	0.18
260°	6.47	0.19
270°	6.55	0.2
280°	6.13	0.19
290°	5.51	0.18
300°	5.11	0.18
310°	4.59	0.18
320°	4.27	0.19
330°	4.0	0.21
340°	3.76	0.23
350°	3.66	0.24

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

