


Crater report 2636 of RG5

General information



ID: 2636

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 123m ± 7.0m

Mean depht: $8.3m \pm 0.6m$

d/D ratio : 0.068 ± 0.006

Circularity index: 0.91

Mean slope: 8.58

Geometric center coordinates: (3643166.002,

221445.566)

 $\label{lowest} \textbf{Coordinates of the crater's lowest point:}$

(3643182.4999999, 221432.4999999907)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	10.2	0.28
10°	9.84	0.27
20°	10.04	0.26
30°	9.79	0.23
40°	10.29	0.24
50°	9.25	0.22
60°	9.01	0.23
70°	8.44	0.25
80°	8.61	0.26
90°	9.25	0.26
100°	8.7	0.24
110°	8.41	0.24
120°	8.18	0.23






130°	8.23	0.2
140°	8.45	0.2
150°	8.63	0.21
160°	8.93	0.22
170°	9.06	0.22
180°	9.45	0.23
190°	8.42	0.22
200°	7.41	0.21
210°	7.47	0.22
220°	7.16	0.2
230°	7.08	0.2
240°	6.35	0.19
250°	7.04	0.2
260°	7.7	0.21
270°	8.6	0.22
280°	8.56	0.21
290°	8.39	0.2
300°	8.21	0.2
310°	8.71	0.2
320°	8.68	0.2
330°	8.64	0.23
340°	8.85	0.24
350°	8.89	0.26

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

