


Crater report 731 of RG5

General information



ID:731

Study area: RG5

Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter : $147m \pm 8.0m$

Mean depht : $3.7m \pm 0.6m$

d/D ratio : 0.025 ± 0.005

Circularity index: 0.9

Mean slope: 2.98

Geometric center coordinates: (3642216.268,

248939.0915)

Coordinates of the crater's lowest point : (3642232.4999999, 248937.49999999013)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	2.04	0.25
10°	1.81	0.25
20°	1.67	0.24
30°	1.78	0.23
40°	2.12	0.22
50°	2.49	0.22
60°	2.52	0.2
70°	2.82	0.2
80°	3.19	0.21
90°	3.55	0.23
100°	3.52	0.21
110°	3.54	0.2
120°	3.55	0.2






130°	3.62	0.19
140°	3.49	0.18
150°	3.31	0.19
160°	3.41	0.2
170°	3.57	0.2
180°	3.81	0.21
190°	3.64	0.19
200°	3.34	0.18
210°	3.28	0.18
220°	3.2	0.18
230°	3.06	0.19
240°	3.06	0.2
250°	3.04	0.2
260°	3.15	0.21
270°	3.3	0.21
280°	3.3	0.2
290°	3.18	0.18
300°	3.08	0.19
310°	3.08	0.19
320°	2.9	0.19
330°	2.5	0.23
340°	2.26	0.24
350°	2.19	0.25

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

