


Crater report 3106 of RG5

General information



ID:3106

Study area: RG5

Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 107m ± 8.0m

Mean depht: $5.7m \pm 0.6m$

d/D ratio : 0.053 ± 0.007

Circularity index: 0.92

Mean slope: 6.78

Geometric center coordinates: (3643421.554,

216934.9492)

Coordinates of the crater's lowest point : (3643437.4999999, 216922.49999999077)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	9.86	0.26
10°	9.37	0.25
20°	8.85	0.25
30°	9.18	0.23
40°	9.06	0.22
50°	8.58	0.22
60°	8.21	0.23
70°	7.71	0.26
80°	7.16	0.26
90°	6.8	0.27
100°	6.13	0.26
110°	5.36	0.25
120°	4.77	0.23






130°	4.84	0.22
140°	4.75	0.22
150°	4.62	0.25
160°	4.72	0.24
170°	4.96	0.26
180°	5.16	0.25
190°	5.0	0.24
200°	5.14	0.24
210°	5.2	0.23
220°	5.3	0.2
230°	5.15	0.22
240°	4.98	0.23
250°	5.28	0.23
260°	6.13	0.24
270°	6.63	0.25
280°	7.04	0.24
290°	6.53	0.25
300°	7.48	0.24
310°	7.95	0.22
320°	8.81	0.24
330°	8.73	0.23
340°	9.14	0.26
350°	9.66	0.27

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

