


# Crater report 3809 of RG5

#### **General information**



**ID**:3809

Study area: RG5 Swirl: on-swirl

Morphology: Bowl-shaped

Mean Diameter: 145m ± 10.0m

Mean depht:  $6.2m \pm 0.6m$ d/D ratio:  $0.043 \pm 0.005$ Circularity index: 0.94

Mean slope: 5.32

Geometric center coordinates: (3638844.767,

207203.7695)

**Coordinates of the crater's lowest point :** (3638852.4999999, 207192.4999999999)

#### Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	6.46	0.24
10°	5.68	0.22
20°	5.36	0.22
30°	4.91	0.2
40°	4.75	0.19
50°	4.73	0.19
60°	4.72	0.2
70°	4.79	0.22
80°	4.92	0.21
90°	5.1	0.23
100°	4.92	0.21
110°	4.93	0.21
120°	5.14	0.19






5.3	0.18
5.11	0.18
4.49	0.19
4.08	0.19
3.99	0.21
3.88	0.22
3.66	0.21
3.61	0.2
3.86	0.19
4.07	0.18
5.16	0.19
5.7	0.2
6.01	0.2
6.49	0.21
6.8	0.22
6.68	0.23
6.23	0.22
6.56	0.21
6.88	0.2
6.99	0.2
6.62	0.21
6.48	0.23
6.32	0.22
	5.11   4.49   4.08   3.99   3.88   3.66   3.61   3.86   4.07   5.16   5.7   6.01   6.49   6.8   6.23   6.56   6.88   6.99   6.62   6.48

### **Topographic roughness index (TRI)**

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





## **Topographic profiles**

