


Crater report 36 of RG5

General information



ID:36

Study area: RG5 Swirl: off-swirl

Morphology: Bowl-shaped

Mean Diameter : $185m \pm 9.0m$

 $\textbf{Mean depht}: 10.3m \pm 0.7m$

d/D ratio : 0.055 ± 0.005

Circularity index : 0.9

Mean slope: 7.55

Geometric center coordinates: (3637076.163,

252283.9201)

Coordinates of the crater's lowest point : (3637082.4999999, 252282.4999999005)

Slopes data

North orientation	Slope (°)	Uncertainty (°)
0/360°	8.33	0.21
10°	8.21	0.19
20°	8.1	0.19
30°	8.32	0.19
40°	8.33	0.17
50°	8.09	0.16
60°	7.12	0.17
70°	6.9	0.18
80°	7.41	0.18
90°	7.81	0.19
100°	7.48	0.18
110°	7.18	0.18
120°	6.92	0.17






130°	6.45	0.17
140°	5.82	0.17
150°	5.57	0.19
160°	5.55	0.21
170°	5.47	0.2
180°	5.81	0.2
190°	5.76	0.2
200°	6.11	0.19
210°	7.19	0.19
220°	7.81	0.18
230°	9.19	0.19
240°	9.34	0.2
250°	9.77	0.21
260°	9.74	0.21
270°	9.57	0.21
280°	9.22	0.21
290°	8.71	0.21
300°	8.05	0.2
310°	7.82	0.19
320°	7.41	0.19
330°	6.75	0.19
340°	6.93	0.2
350°	7.72	0.2

Topographic roughness index (TRI)

L'indice TRI est un indice permettant de blablabla bla. Lorem ipsum lorem ipsum. hiefneianslbf phsefibbslvbskib ohsgshrpvnfb shvlihvgsihv hp;sovbns





Topographic profiles

